App. B: Petrie Decl., Ex. 2 Part III

12150	700	N/A	3006 SPRG	12-Mar-76	N	s	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501409	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12148	700	84364	308 WIN	2-Jan-13	N	s	10-Jul-15	10-Jul-15	Fired on Safe Release	Could Not Duplicate Concern	501318	F	Per Ilion - Replace TA & test @ n/c
12142	700	25803	7MM REM	20-Jan-03	N	s	10-Jul-15	10-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501355	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
	700		223 REM			-				Could Not Duplicate	*****		Per Ilion - Repair at n/c, XMP
12157	700	84370 29717	3006 SPRG	20-Apr-09 24-Feb-03	N	s	14-Jul-15	14-Jul-15	Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	501431 501456	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
													Per Ilion, replace trigger assembly, check over, and
12158	700	N/A	308 WIN	15-Jun-81	N	S	14-Jul-15	14-Jul-15	Fired With Safe ON	Improper Maintenance	501476	F	test fire at no charge
12156	887	82500	12 GA	13-Nov-13	N	5	14-Jul-15	14-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501426	F	Per Ilion - Repair at n/c
12154	Para RECON 9	96699	9MM	7-Jan-15	N	s	14-Jul-15	14-Jul-15	Fired Out of Battery	Could Not Duplicate Concern Altered Adjustments or	501472	F	Per Ilion - Repair at n/c
12170	700	not avail.	17 REM	4-May-72	N	S	16-Jul-15	16-Jul-15	Fired on Bolt Closing	Components	501624	F	Per Ilion - Repair at n/c
12167	700	27119	243 WIN	2-Nov-11	N	s	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501563	F	Per Ilion - Repair at n/c, XMP update
									Unexplained Discharge - No Mention of Safety	Could Not Duplicate			
12171	700	not avail.	270 WIN 3006 SPRG	19-Apr-80 3-Mar-93	N	S	16-Jul-15	16-Jul-15	Position Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	501562 501561	F	Per Ilion - Repair at n/c Per Ilion, replace trigger assembly, check over, and test fire at no charge
12165	700	N/A	3006 SPRG	3-Jun-80	N	5	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501625	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12169	700	N/A	3006 SPRG	8-Dec-70	N	S	16-Jul-15	16-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501622	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12175	700	84218	308 WIN	21-Nov-12	N	PI/S	16-Jul-15		Fired on Bolt Closing	Other - Unexamined		F	
12179	CARBON 15	90806	223/5.56	1-May-13	N	PD/S	17-Jul-15		Unexplained Discharge - No Mention of Safety Position	Other - Unexamined Could Not Duplicate		F	
12186	700	85334	243 WIN	28-Aug-13	N	s	20-Jul-15	20-Jul-15	Fired on Bolt Closing	Concern	501688	F	Per Ilion - Repair at n/c
12184	700	25849	25-06 REM	15-Jun-98	N	s	20-Jul-15	20-Jul-15	Other - Firearms - XMP Update	Sent in for Evaluation	501687	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12183	700	29711	280 REM	16-Oct-92	N	s	20-Jul-15	20-Jul-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	501690	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

12182	700	60201	3006 SPRG	1-Jul-65	N	S	20-Jul-15	20-Jul-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	501650	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12185	700	N/A	3006 SPRG	17-Sep-81	N	s	20-Jul-15	20-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501689	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
	700		7MM REM			9	201145	20-Jul-15	Other - Firearms -	Could Not Duplicate		F	Per Ilion, replace trigger assembly, check over, and
12187	700	not avail.	7MM REM	27-Feb-80	N	5	20-Jul-15	20-Jul-15	XMP Update Other - Does not	Concern Could Not Duplicate	501686	- 1	test fire at no charge
12188	700	not avail.	MA	2-Apr-80	N	s	20-Jul-15	20-Jul-15	trust firearm	Concern	501685	F	Per Ilion - Repair at n/c
12181	700 ML	27572	50 CAL	28-Sep-96	N	s	20-Jul-15	20-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501684	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
										Other - Unspecified or Undetermined -			Replace with Ramac 70701 in
12193	597	26516	17 HMR	31-Jan-03	N	PI/PD/S	20-Jul-15	19-Aug-15	My Gun Blew Up	Ammunition Could Not Duplicate	502587	F	exchange
12197	660	not avail.	243 WIN	1-Feb-68	Υ	5	22-Jul-15	22-Jul-15	Fired on Bolt Closing	Concern	501872	F	Per Ilion - Repair at n/c
12205	673	24687	350 REM MA	18-Jun-03	N	S	22-Jul-15	22-Jul-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	501792	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12198	700	N/A	22-250 REM	14-Feb-81	N	S	22-Jul-15	22-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501796	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12201	700	not avail.	243 WIN	5-May-71	N	s	22-Jul-15	22-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501794	F	Per Ilion - Repair at n/c
12195	700	N/A	270 WIN	24-Sep-71	N	5	22-Jul-15	22-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501790	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12199	700	not avail.	3006 SPRG	29-Apr-74	N	s	22-Jul-15	22-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501791	F	Per Ilion - Repair at n/c
12204	700	N/A	3006 SRPG	3-Feb-72	N	5	22-Jul-15	22-Jul-15	Fired on Safe Release	Altered Adjustments or Components	501789	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12200	887	82500	12 GA	7-Jul-09	N	5	22-Jul-15	22-Jul-15	Fired Out of Battery	Sent in for Evaluation	501815	F	Per Ilion, check over completely, repair as needed, and test at no charge.
12203	700	20000	7MM MAG		N	PD/S	22-Jul-15	7-Aug-15	Unexplained Discharge - No Mention of Safety Position	Other - Unexamined	n/a	F	No further contact from customer
	17000000					1000				Could Not Duplicate	140	Ť	Sunoine.
12206	710	27410	3006 SPRG	9-Aug-06	Υ	S	22-Jul-15	6-Aug-15	Fired on Bolt Closing Delayed Firing -	Concern Could Not Duplicate	501793	F	Replace w/85846 in exchange
12214	700	27476	270 WIN	19-Aug-95	N	PD/S	24-Jul-15	24-Jul-15	Firearms	Concern	501930	F	Per Ilion - Repair at n/c
12213	700	84401	25-06 REM	16-Feb-09	N	s	24-Jul-15	24-Jul-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	501928	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12211	700	N/A	270 WIN	22-Jul-74	N	s	24-Jul-15	24-Jul-15	Fired on Bolt Opening	Improper Maintenance	501931	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

12216	700	not avail.	270 WIN	19-May-69	N	S	24-Jul-15	24-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501932	F	Per Ilion - Repair at n/c
12218	700	not avail.	3006 SPRG	13-Aug-75	N	S	24-Jul-15	24-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	501934	F	Per Ilion - Repair at n/c
									Other - Firearms -	Could Not Duplicate			Per Ilion - Repair at n/c, XMP
12220	700	27095	3006 SPRG	6-Sep-07	N	S	24-Jul-15	24-Jul-15	XMP Update	Concern	501927	F	update
12210	700	N/A	308 WIN	1-Feb-84	N	s	24-Jul-15	24-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501929	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12219	700	not avail.	7MM REM MA	21-Sep-76	N	s	24-Jul-15	24-Jul-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501933	F	Per llion - Repair at n/c
12215	887	82501	12 GA	2-Mar-10	N	s	24-Jul-15	24-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501902	F	Per Ilion, check over completely, repair as needed and test at no charge.
12212	710	27410	3006 SPRG	29-Jul-03	Y	S	24-Jul-15	18-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	501925	F	Replace with Ramac 85846 in exchange
										ACT - \$250000 - 100			Per Ilion, replace trigger
12222	700	N/A	3006 SPRG	25-Aug-78	N	s	28-Jul-15	28-Jul-15	Fired on Safe Release	Altered Adjustments or Components	501970	F	assembly, check over, and test fire at no charge
12223	700	84207 85657	308 WIN 7MM REM	17-Mar-12	N Y	s	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position Other - Firearms	Could Not Duplicate Concern Altered Adjustments or Components	502001	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge Replace with Ramac 85848 in exchange
12230	770	85657	IVIA	T-Man-To	- 1	3	28-JUI-15	19-Aug-15	Other - Firearms	Components	502026	- 1	Consumer Service replacing
12227	597	26516	17 HMR	4-May-06	N	s	28-Jul-15	28-Jul-15	Other + Firearms	Sent in for Evaluation	502013	F	in exchange with Ramac 70701
12235	700	27512	22-250 REM	23-Jul-99	N	s	28-Jul-15	28-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	502032	F	Per Ilion - Repair at n/c
12233	700	2/312	KEIVI	23-701-33	19	3	50-301-13	20-301-13	Delayed Firing -	Could Not Duplicate	302032	- 1	ret mon - Repair at nye
12236	700	25825	223 REM	16-Feb-89	N	S	28-Jul-15	28-Jul-15	Firearms	Concern	502034	F	Per Ilion - Repair at n/c
-77.6			Lac Trans						d or nesseri	Could Not Duplicate			
12234	700	27119 N/A	243 WIN	28-Feb-06 20-Aug-79	N	PI/S	28-Jul-15 28-Jul-15	28-Jul-15 28-Jul-15	Fired on Safe Release Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	502039	F	Per Ilion - Repair at n/c Per Ilion, replace trigger assembly, check over at no charge
12233	700	25864	270 WIN	12-Jan-84	N	s	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	502035	F	Per Ilion - Repair at n/c
													Per Ilion - Repair at n/c, XMP
12228	700	85338	300 WIN MA	25-Oct-12	N	s	28-Jul-15	28-Jul-15	Other - Firearms - XMP Update	Sent in for Evaluation	502000	F	update, Ck for \$20.51 for shipping refund
12224	700	25773	3006 SPRG	21-Jul-88	N	s	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502030	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12231	700	not avail.	3005 500 5	20-Mar-80	N	5	28-Jul-15	70 1.4 15	Fired on Safe Release	Sent in for Evaluation	502040	F	Per Ilion - Repair at n/c

12232	700	not avail.	3006 SPRG	4-Jun-74	N	s	28-Jul-15	28-Jul-15	Unexplained Discharge Safe OFF	Altered Adjustments or Components	502033	F	Per Ilion - Repair at n/c
12229	700	27572	50 CAL	28-May-96	N	S	28-Jul-15	28-Jul-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502036	F	Per Ilion, replace trigger assembly, check over at no charge
12225	700	N/A	6MM REM	21-Mar-69	N	s	28-Jul-15	28-Jul-15	Fired on Bolt Closing	Could Not Duplicate Concern	501999	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12237	700	not avail.	7MM REM MA	12-Jul-79	N	s	28-Jul-15	28-Jul-15	Fired With Safe ON	Altered Adjustments or Components	502037	F	Per Ilion - Repair at n/c
				1000						Could Not Duplicate			Per Ilion, replace trigger assembly, check over, and
12226	SEVEN 700	N/A	6MM REM	1-Jul-83	N	S	28-Jul-15	28-Jul-15	Fired on Safe Release	Concern Could Not Duplicate	502031	F	test fire at no charge
12254		25714	223 REM	26-Feb-15	N	S	4-Aug-15	4-Aug-15	Fired on Bolt Closing	Concern Altered Adjustments or	502159	F	Per Ilion - Repair at n/c
12260	700	not avail. 85335	223 REM 270 WIN	22-Dec-76 2-Oct-12	N N	S	4-Aug-15		Fired on Safe Release Fired on Bolt Closing	Components Could Not Duplicate Concern	502144	F	Per Ilion - Repair at n/c Per Ilion - Repair at n/c, XMF update
12258	700	27121	270 WIN	10-May-12		5	4-Aug-15	4-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502141	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
									Unexplained Discharge - No Mention of Safety				
12257	700	25632	280 REM	17-Apr-87	N	S	4-Aug-15	26-Aug-15	Position Other - Firearms -	Sent in for Evaluation Altered Adjustments or	502084	F	Per Ilion - Repair at n/c Per Ilion - Repair at n/c, XMI
12251	700	85367	300 RUM	21-Apr-07	N	S	4-Aug-15	4-Aug-15	XMP Update	Components	502110	F	update
12252	700	25634	3006 SPRG	16-Mar-89	N	S	4-Aug-15	27-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502146	F	Per Ilion - Repair at n/c
12255	700	not avail.	3006 SPRG	19-Jan-88	N	s	4-Aug-15	21-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502142	F	Per Ilion - Repair at n/c
12262	700	not avail.	3006 SPRG	15-May-81	N	s	4-Aug-15	19-Aug-15	Unexplained Discharge Safe ON	Sent in for Evaluation	502143	F	Per Ilion - Repair at n/c
12250	700	27499	308 WIN	23-Feb-01	N	s	4-Aug-15	21-Aug-15	Fired on Safe Release	Could Not Duplicate Concern	502112	F	Per Ilion - Repair at n/c
12253	700	not avail.	308 WIN	18-Jan-72	N	5	4-Aug-15	4-Aug-15	Other - Firearms - XMP Update	Sent in for Evaluation	502112	F	Per Ilion - Repair at n/c, XMI update
12261	770	85632	270 WIN	15-Jul-08	Υ	5	4-Aug-15	4-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502145	F	Consumer Service replaced with Ramac 85844 in exchange
12262	700	20707	222.051.5	22 5-1-51					Fixed as Balticle	Could Not Duplicate	502254	-	Per Ilion - Repair at n/c, XMI
12267	700	29703 N/A	223 REM 3006 SPRG	23-Feb-01	N	5	5-Aug-15		Unexplained Unexplained Discharge - No Mention of Safety Position	Concern Improper Maintenance	502254	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12275	700	N/A 25793		27-Aug-86		s	5-Aug-15		Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502253	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

12279	597	26516	17 HMR	10-Jul-05	N	PD/S	6-Aug-15	1-Sep-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	503099	F	Replace with Ramac 70712 in exchange
12615	M-4	n/a	223		N	s/c	6-Aug-15	30-Oct-15	Barrel Damaged/Bulged (Other than Burst)	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke to replace ammuniton to Fletc for return SNCS2,890.71
12282	700	84215	223 REM	9-Mar-10	N	s	10-Aug-15	28-Aug-15	Unexplained Discharge - No Mention of Safety Position	AFT MKT TRIGGER ASSM	502401	F	Per Ilion - Repair at n/c - goodwill
12287	700	not avail.	270 WIN	17-Nov-81	N	S	10-Aug-15	31-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502402	F	Per Ilion- repair at no charge
12281	700	not avail.	7MM REM MA	1-Jun-62	N	s	10-Aug-15	28-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502404	F	Per Ilion - Repair at n/c
12291	710	27410	3006 SPRG	9-Dec-03	Y	s	10-Aug-15	10-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	502354	F	Replace with Ramac 85846 in exchange
12291	700	not avail.	3006 SPRG	9-Dec-03	N	PI/S	10-Aug-15	-	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502354		exchange Per Ilion- Repair at no charge
12285	700	not avail.	25-06 REM	3-Feb-71	N	s	10-Aug-15	1-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502352	F	Per Ilion- repair at no charge
12284	700	not avail.	300 WIN	8-Apr-80	N	5	10-Aug-15	1-Sep-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502351	F	Per Ilion- repair at n/c
12283	770	85635	7MM REM MA	26-Aug-08	Y	5	10-Aug-15	9-Sep-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	502353	F	Replace w/85848 in exchange through SNC order
12286	SPORTSMAN 78	26172	223 REM	20-Mar-89	Y	S	10-Aug-15	11-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	502403	F	Per Ilion- repair at no charge
12310	Rossi single shot	n/a	22 LR		N	PI/S		20-Aug-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	n/a	A	Lonoke - replaced ammo
12296	1187	29879	12 GA	8-Aug-12	N	5	12-Aug-15		Unexplained Discharge Safe OFF	Other - Unexamined Could Not Duplicate		F	
12301 12303	700 750	25818 27057	308 WIN	11-Aug-89 20-Feb-14	N N	5		13-Aug-15		Concern Could Not Duplicate Concern	502445 502416	F	Per Ilion- repair at n/c Per Ilion- Check over completely
12302	887	82500	12 GA	23-Jun-14	N	s		13-Aug-15		Sent in for Evaluation Could Not Duplicate	502420	F	Per Ilion-repair as needed at n/c
12300	700	not avail.	243 WIN	29-Jan-73	N	s	13-Aug-15	1-Sep-15	XMP Update Other - Firearms -	Concern Could Not Duplicate Could Not Duplicate	502447	F	Per Ilion- repair at n/c
12299	700	not avail.	3006 SPRG	24-May-73	N	S	13-Aug-15	1-Sep-15	XMP Update	Concern	502446	F	Per Ilion- repair at n/c

		_						_	The section of				
	622000	9 60			223			22450	Unexplained Discharge - No Mention of Safety	Not Examined by Product			Rifle not returned to Ilion fo
12309	700	not avail.			N	PD/S	14-Aug-15	19-Feb-16	Position	Service Could Not Duplicate	n/a	F	exam
12316	700	not avail.	3006 SPRG	20-Feb-79	N	s	17-Aug-15	17-Aug-15	Fired on Bolt Closing	Concern	502543	F	Per Ilion- repair at n/c.
12314	700	84207	308 WIN	17-Jun-13	N	s	17-Aug-15	17-Aug-15	Fired With Safe ON	Could Not Duplicate Concern	502542	F	Per Ilion- repair at n/c
	700	25720	2001444							Could Not Duplicate	503440		
12317	700	25739	308 WIN	3-May-10	N	S	17-Aug-15	17-Aug-15	Unexplained Discharge - No Mention of Safety	Concern Could Not Duplicate	502449	F	Per Ilion- repair at n/c
12315	700	not avail.	MA	1-Sep-67	N	S	17-Aug-15	3-Sep-15	Position	Concern	502544	F	Per Ilion-repair at no charge
										Could Not Duplicate		-17	
12324	700	not avail.	3006 SPRG	10-Jun-78	N	S	19-Aug-15	19-Aug-15	Fired on Safe Release	Concern Could Not Duplicate	502630	F	Per Ilion- Repair at no charge
12325	700	25715	308 WIN	15-Nov-99	N	s	19-Aug-15	26-Aug-15	Fired on Bolt Closing	Concern	502631	F	Per Ilion-repair at n/c
12322	770	85649	243 WIN	20-Sep-12	Y	s		19-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502591	F	Consumer Service replaced with Ramac 85842 in exchange
12326	700	not avail.	270 WIN	2-Feb-79	N	PD/S	19-Aug-15	2-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502590	F	Per Ilion- repair at n/c.
			7MM-08					7.5		Could Not Duplicate		10	43 32
12320	SEVEN	24741	REM	12-Jul-02	N	S	19-Aug-15	1-Sep-15	Fired on Safe Release	Concern	502689	F	Per Ilion- Repair at no charge
12342	700	84020	257 ROBERT	10-Aug-09	N	s	24-Aug-15	24-Aug-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	502802	F	Per Ilion- Replace TA and test
12347	700	not avail.	280 REM	1-Jul-66	N	s	24-Aug-15	31-Aug-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	502756	F	Per Ilion- Repair as needed
									Unexplained	Could Not Duplicate			
12343	700	26129	3006 SPRG	21-Oct-98	N	S	24-Aug-15	31-Aug-15	Discharge Safe OFF	Concern	502805	F	Per Ilion- Replace TA and test
12340	770	85633	3006 SPRG	22-Jul-11	Y	5	74. Aug. 15	24-Aug-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	502803	F	Replace with Ramac 85846 in exchange
12540	770	0,000	3000 31 110	22.70(-11	·		E4 Mug-23	24-Mag-13	Foation	Could Not Duplicate	302003		Replace with Ramac 85846 in
12344	770	85633	3006 SPRG	3-Jan-14	Υ	s	24-Aug-15	24-Aug-15	Fired on Safe Release Fired on Bolt	Concern Could Not Duplicate	502712	F	exchange
12341	700	not avail.	222 REM	1-Feb-64	N	s	24-Aug-15	2-Sep-15	Opening	Concern	502757	F	Per Ilion- Repair TA and test
12339	700	not avail.	270 WIN	5-Oct-72	N	s	24-Aug-15	3-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	502804	F	
										Could Not Duplicate		T	Per Ilion- Check over
12335	ACR	90838	223/5.56	24-Sep-13	N	s	24-Aug-15	24-Aug-15	Went Automatic	Concern	502811	F	completely Per Ilion- Check over
12337	ACR	90838	223/5.56	1-Feb-13	N	s	24-Aug-15	24-Aug-15	Went Automatic Unexplained	Sent in for Evaluation Could Not Duplicate	502761	F	completely and repair as needed
12362	700	not avail.	243 WIN	20-Nov-75	N	PD/S	25-Aug-15	31-Aug-15	Discharge Safe ON	Concern	502915	F	Per Ilion- Replace TA and test
12351	700	27269	3006 SPRG	7-Jan-14	N	s	-	25-Aug-15		Could Not Duplicate Concern	502862	F	Per Ilion- Replace TA and test
	700	Long Grown	2000 0000				20.0		Other - Firearms -	Could Not Duplicate	503010		Davidson Davidson TA
12358	700	not avail.	3006 SPRG	14-Jan-75	N	S		31-Aug-15	XMP Update	Concern Could Not Duplicate	502910		Per Ilion- Replace TA and test
12361	700	not avail.	3006 SPRG 300 WIN	18-Aug-80	N	S	25-Aug-15	25-Aug-15	Fired With Safe ON	Concern Altered Adjustments or	502913	F	Per Ilion-Replace TA and test Per Ilion-Replace with 783 at
12355	710	27414	MA	18-Jul-05	Y	s	1		Fired on Bolt Closing	Components	502861	F	N/C

			2000 - 177 TOTA							Could Not Duplicate			
12364	770	85634	308 WIN	12-Nov-12	Y	S	25-Aug-15	25-Aug-15	Excessive Headspace	Concern	502918	F	Per Ilion- Repair as needed
access.				ersonalaises-n		300000			Anna markettur	Could Not Duplicate			
12356	700	not avail.	25-06 REM	14-Jul-78	N	PD/S	25-Aug-15	3-Sep-15	Fired on Bolt Closing	Concern	502914	F	Per Ilion- Replace TA and te
			22-250						Other - Firearms -	Could Not Duplicate			
12353	700	not avail.	REM	12-Jul-77	N	PI/5	25-Aug-15	8-Sep-15	XMP Update	Concern	502912	F	Per Ilion- Replace TA and te
										Altered Adjustments or		-10	
12359	700	not avail.	270 WIN	5-May-80	N	5	25-Aug-15	11-Sep-15	Fired on Safe Release	Components	502916	F	Per Ilion- Replace TA and tes
	-000									Could Not Duplicate			
12352	700	26098	3006 SPRG	8-May-92	N.	S	25-Aug-15	8-Sep-15	Fired on Safe Release	Concern	502908	F	Per Ilion- Replace TA and tes
				1 1			-5.4						
									Unexplained	Could Not Duplicate		- 117	
12360	700	25859	3006 SPRG	24-Apr-00	N	S	25-Aug-15	1-Sep-15	Discharge Safe OFF	Concern	502909	F	Per Ilion-Repair as needed
									Other - Firearms -	Could Not Duplicate			
12357	700 ML	27580	50 CAL	10-Jul-96	N	S	25-Aug-15	8-Sep-15	XMP Update	Concern	502911	F	Per Ilion- Replace TA and tes
			attraction rest										Per Ilion, replace trigger
			7MM-08							Could Not Duplicate		- 117	assembly, check over, and
12370	700	27357	REM	27-Jan-14	N	S	27-Aug-15	15-Sep-15	Fired on Bolt Closing	Concern	503660	F	test fire at no charge
									Delayed Firing -	Could Not Duplicate			
12374	700	25789	25-06 REM	13-Mar-87	N	S	28-Aug-15	28-Aug-15	Firearms	Concern	503014	F	Per Ilion- Replace TA and tes
			300 WIN						Other - Firearms -	Could Not Duplicate			
12380	700	27099	MA	19-Mar-13	N	s	28-Aug-15	28-Aug-15	XMP Update	Concern	503060	F	Per Ilion- Replace TA and tes
	7.000		7227		-				*************		27,000,000,000		
12375	700	86463	308 WIN	11-Dec-14	N	S	28-Aug-15	28-Aug-15	Fired on Safe Release	Sent in for Evaluation	503056	F	Per Ilion- Replace TA and tes
										Could Not Duplicate			
12381	700	27474	243 WIN	5-Jun-02	N	PI/PD/S	28-Aug-15	9-Sep-15	Fired on Safe Release	Concern	503068	F	Per Ilion- Replace TA and tes
AKUUA	3,00		2,52,1111	5 3411 02		1410/5	EU HUB EU	2 ocp 25	Unexplained		303000	-	The state of the s
									Discharge - No			- 117	
									Mention of Safety	Could Not Duplicate		- 117	
12376	700	25791	270 WIN	24-Aug-90	N	s	29 Aug 15	11-Sep-15	Position	Concern	503067		Per Ilion- Replace TA and tes
123/0	700	23/31	270 99119	24-MUR-30	14		50-MUR-13	11-3ep-15	Unexplained	Concern	303007	- 6	rei mon neplace i'A and tes
									Discharge - No			- 117	
									Mention of Safety	Card Net Durlings		- 117	
	700	26010	300 RUM	2-Feb-04	N	s	20.4 - 45		Position of Safety	Could Not Duplicate	503066		Boother Booker Talendan
12377	700	26010	300 KUW	2-Feb-04	IN	5	28-Aug-15	11-Sep-15	and the state of t	Concern	503066	- 1	Per Ilion- Replace TA and tes
									Unexplained			- 117	
									Discharge - No	122002222000000000		- 117	
								10000114	Mention of Safety	Altered Adjustments or		1.0	
12379	700	not avail.	3006 SPRG	7-Oct-70	N	5	28-Aug-15	3-Sep-15	Position	Components	503059	F	Per Ilion- Replace TA and tes
120001999	SPORTSMAN	22327	-300000000			18	200-002	225 72		Altered Adjustments or	1200224	13	
12378	78	26164	3006 SPRG	17-Jul-87	Y	S	28-Aug-15	8-Sep-15	Fired on Safe Release	Components	503061	F	Per Ilion- Replace TA and tes
									Unexplained				
									Discharge - No	ASSOCIATION -		- 117	
er o ressu			0.0000.00000	100 Sel 1000 (100 Se		5777000	ALTERNATION TO STATE		Mention of Safety	Could Not Duplicate			Per Ilion- Check over
12387	870	25098	12 GA	19-Jul-13	N	PD/S	31-Aug-15	24-Sep-15	Position	Concern	504037	F	completely
													Per Ilion- Check over
												-10	completely and repair as
12392	770	85634	308 WIN	14-Feb-14	Y	PD/S	1-Sep-15	1-Sep-15	Broken Part	Sent in for Evaluation	503171	F	needed
			257							Could Not Duplicate			
12394	700	25600	ROBERT	2-May-91	N	s	1-Sep-15	1-Sep-15	Fired on Bolt Closing	Concern	503098	F	Per Ilion- Replace TA and tes
	H&R			1771					177				Per Ilion- Repair or replace a
	PARDNER	72282	20 GA	3-May-14	N	S	1-Sep-15	1-Sep-15	Fired With Safe ON	Sent in for Evaluation	503125	F	needed
12393													Per Ilion- Check over
12393													completely and repair as
12393				1223400000	N	S	1-Sep-15	1-Sep-15	Fired With Safe ON	Sent in for Evaluation	503186	F	needed
12393 12390	CARBON 15	90689	223/5.56	16-May-13				Josep Au				- 1	
	CARBON 15	90689	223/5.56	16-May-13	14								
12390				2000 200		20	1-Sep-15	1-Sen-15	Receiver Damaged	Over pressured shell	503185	E	Per Ilion-Replace at 1/2 cos
	CARBON 15 XM15-E2S	90689 not avail.	223/5.56	28-Sep-06	N	s	1-Sep-15	1-Sep-15	Receiver Damaged	Over pressured shell	503185	F	Per Ilion- Replace at 1/2 cos
12390				2000 200		20	1-Sep-15	1-Sep-15	Receiver Damaged	Over pressured shell Other - Unspecified or Undetermined -	503185	F	Per Ilion- Replace at 1/2 cos Consumer Service replacing in exchange with Ramac

	add a factor of	(www.e	\$40 KONSONON ***			ar su toer			Unexplained Discharge - No Mention of Safety	Could Not Duplicate	-0.0000000		Repair @ n/c under XMP
12407	700	27094	270 WIN	8-Aug-07	N	PD/S	3-Sep-15	18-Sep-15	Position	Concern	503225	F	
12404	870	25571	12 GA	6-Feb-89	N	PD/S	3-Sep-15	14-Sep-15	Fired With Safe ON	Fired from Contact with Foreign Object	503213	F	
										6 111111 8 11111			Per Ilion- Check over
12405	870	25571	12 GA	6-Feb-89	N	PD/S	3-Sep-15	3-Sep-15	Fired With Safe ON	Could Not Duplicate Concern	503215	F	completely and repair as needed
12403	870	233/1	12 04	9-160-03	14	PU/S	3-3ep-13	3-3cp-13	Unexplained	Concern	303213	1	needed
12402	700	27269	3006 SPRG	12-Aug-05	N	PI/S	3-Sep-15	3-Sep-15	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503224	F	Repair @ n/c
our or co	NUMBER	- destruction	201200000	August 100	08000	62	200 mm 1000	turners on the	0800000000000000000	Altered Adjustments or	10000000000		
12408	700	not avail.	243 WIN 7MM REM	23-Jan-73	N	S	3-Sep-15	3-Sep-15	Other - Firearms	Components	503216	F	Per Ilion- Replace TA and test
12409	700	not avail.	MA	24-May-76	N	s	3-Sep-15	3-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503251	F	Per Ilion- Replace TA and test
12406	721	not avail.	3006 SPRG	1-Aug-69	Υ	5	3-Sep-15	22-Sep-15	Fired on Bolt Closing	Sent in for Evaluation	503267	F	Per Ilion- Replace TA and test
12400	870	25571	12 GA	6-Feb-89	N	s	3-Sep-15	3-Sep-15	Fired With Safe ON	Could Not Duplicate Concern	503214	F	Per Ilion- Check over completely and repair as needed
12399	887	82500	12 GA	15-Feb-10	N	s	3-Sep-15	3-Sep-15	Fail to Fire	Could Not Duplicate Concern	503237	F	Per Ilion- Check over completely and repair as needed
antown	1020474	50/85 F00	39479,000N	574 6 + 0.5 15		201500	- AS	10000000	massecretas-cott	Could Not Duplicate	2005/100000		5550 To - 1- 15552 - 10
12416	597	26516	17 HMR	15-Oct-03	N	PD/S	9-Sep-15	9-Sep-15	My Gun Blew Up	Concern	503395	F	
12422	870	25077	12 GA	14-May-13	N	PD/S	9-Sep-15	9-Sep-15	My Gun Blew Up	Could Not Duplicate Concern	503346	F	Per Ilion- Check over completely and repair as needed
12414	R-15	60005	223 REM	25-Nov-08	N	PD/S	9-Sep-15	9-Sep-15	My Gun Blew Up	Over pressured shell	503357	F	Returned as Received as requested by customer
12415	700	not avail.	270 WIN	19-Sep-84	N	PI/S	9-Sep-15	16-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503367	F	Repair @ n/c
									Fired on Bolt	Could Not Duplicate			
12418	700	not avail.	243 WIN	15-Feb-71	N	S	9-Sep-15	29-Sep-15	Opening	Concern	503419	F	Per Ilion- Replace TA and test
12419	700	not avail.	243 WIN	15-Oct-77	N	s	9-Sep-15	24-Sep-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	503977	F	Per Ilion - Replace TA & test @ n/c
12417	700	84014	270 WIN	6-Jun-13	N	s	9-Sep-15	9-Sep-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	503451		Per Ilion- Replace TA and test
12420	700	not avail.	3006 SPRG	7-May-74	N	5	9-Sep-15	29-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503421		Per Ilion- Replace TA and test
12421	SEVEN	24741	7MM-08 REM	22-Jul-97	N	5	9-Sep-15	16-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503450	F	Per Ilion- Replace TA and test
12424	Para Expert	96745	45 AUTO	11-Dec-14	N	5	10-Sep-15	16-Nov-15	Fired Out of Battery	Sent in for Evaluation	504208	F	Per Release - Replace w/96323 in exchange
12425	887	82500	12 GA	7-Oct-09	N	PD/S	11-Sep-15	2-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	504558	F	
12434	597	26513	22 LR	19-Mar-13	N	PD/S	14-Sep-15	14-Sep-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	503516	F	Per Ilion- Check over completely and repair as needed
12429	700	not avail.	270 WIN	24-Apr-80	N	s	14-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503537	F	Per Ilion- Replace TA and test

										Could Not Duplicate			
12436	700	not avail.	270 WIN	20-Jul-78	N	S	14-Sep-15	14-Sep-15	Fired on Safe Release	Concern Could Not Duplicate	503473	F	Per Ilion- Replace TA and tes
12428	700	not avail.	3006 5PRG	5-Mar-80	N	s	14-Sep-15	14-Sep-15	Fired on Bolt Closing	Concern	503539	F	Per Ilion- Replace TA and tes
12432	700	25793	3006 SPRG	8-Dec-82	N	s	14-Sep-15	30-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503540	F	Per Ilion- Replace TA and tes
12433	700	not avail.	3006 SPRG	1-Apr-72	N	s	14-Sep-15	14-Sep-15	Fired on Safe Release	Improper Maintenance	503501	F	Per Ilion- Replace TA and tes
										Altered Adjustments or			
12435	700	not avail.	3006 SPRG	16-Jul-73	N.	S	14-Sep-15	14-Sep-15	Fired on Safe Release	Components	503496	F	Per Ilion- Replace TA and tes
12430	700	27523	308 WIN	10-May-00	N	s	14-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	503568	F	Per Ilion- Replace TA and tes
12431	870	25568	12 GA	10-Mar-14	N	s		14-Sep-15	Fail to Fire	Could Not Duplicate Concern	503536	F	Per Ilion- Check over completely and repair as
	DPMS G2												Per Ilion- Replace w/60238 in
12427	HUNTER	60238	7.62 X 51	7-Apr-15	N	PD/S	14-Sep-15	6-Oct-15	Fired Out of Battery	Over pressured shell	503586	F	exchange
12438	887	82500	12 GA	19-Jun-13	N	PI/S	14-Sep-15	- 4	Fired With Safe ON	Other - Unexamined		F	
12440	700	27514	223 REM	21-Jul-99	N	S	15-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503642	F	Per Ilion- Replace TA and tes
12439	700	85435	243 WIN	18-May-12	N	s	15-Sep-15	15-Sep-15	Fired on Safe Release	Could Not Duplicate Concern	503634	·	Per Ilion- Replace TA and tes
12433		63433					15-349-15	15-3cp-15	Unexplained Discharge - No Mention of Safety	Altered Adjustments or	303034	ĺ	Per mon- replace to and tes
12441	700	not avail.	243 WIN	25-Mar-69	N	5	15-Sep-15	30-Sep-15	Position	Components	503675	F	Per Ilion- Replace TA and tes
12442	700	not avail.	270 WIN	8-Jan-85	N	5	15-Sep-15	15-Sep-15	Fired on Bolt Closing	Improper Maintenance	503676	F	Per Ilion- Replace TA and tes
12443	700	25774	308 WIN	15-Feb-83	N	s	15-Sep-15	15-Oct-15	Other - Does not trust firearm	Could Not Duplicate Concern	503643	F	Per Ilion- Replace TA and tes
12444	SEVEN	24741	7MM-08 REM	29-Mar-95	N	s	15-Sep-15	15-Oct-15	Unexplained Discharge Safe OFF	Could Not Duplicate Concern	503700	F	Per Ilion- Replace TA and tes
										Other - Unspecified or Undetermined -			
12448	597	26513	22 LR	7-Dec-12	N	PD/S	17-Sep-15	17-Sep-15	Receiver Damaged	Ammunition	503763	F	Per Ilion- Repair as needed
12446	700 ML	27572	50 CAL	28-Apr-97	N	PI/S		30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern Altered Adjustments or	503761		Per Ilion- Replace TA and tes
12447	700	not avail.	243 WIN	3-Jun-76	N	S	17-Sep-15	17-Sep-15	Fired on Safe Release	Components	503777	F	Per Ilion- Replace TA and tes Per Ilion- Check over
		20000						12/25/10/2		Could Not Duplicate			completely and repair as
12445	887	82500	12 GA	17-Dec-13	N	5	17-Sep-15	17-Sep-15	Fired on Bolt Closing Unexplained	Concern	503760	F	needed
12454	700	not avail.	270 WIN	17-Aug-79	N	s	21-Sep.15	30-Sep-15	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503810	E	Per Ilion- Replace TA and tes
12452	700	25773	3006 SPRG	5-Jan-02	N	5		30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	503809		Per Illion- Replace TA and tes
	KONTON			STREET, WILLIAM		100		2522545	Accordance to the second	A A STORY IN THE A STORY AND A STORY IN	11.00 (Del Neth L.)		Per Ilion- Quote to repair or
12451	1100	25332	12 GA	18-Jul-77	N	5	21-Sep-15	21-Sep-15	My Gun Blew Up	Sent in for Evaluation	503914	F	replace

12459	700 ML	27580	50 CAL	24-Jul-96	N	s	21-Sep-15	30-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	503913	F	Per Ilion- Replace TA and test
12458	700	26352	8MM MAUSER	11-Nov-03	N	s	21-Sep-15	1-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	503912		Per Ilion- Replace TA and tes
12453	710	27410	3006 SPRG	12-Apr-01	Y	s	21-Sep-15	13-Oct-15	Fired on Safe Release	Sent in for Evaluation	503924	F	Per Ilion-Replace with 783 in exchange
12464	CARBON 15	90689	223/5.56	11-Mar-13	N	s	22-Sep-15	22-Sep-15	Case Failure	Over pressured shell	503834		Per Ilion- Replace at 1/2 cost
32.10.7			220/0.00			_			Ammunition			1	
12469	547	87971	17 HMR	4-Feb-15	N.	s	24-Sep-15	24-Sep-15	Exploded	Sent in for Evaluation	503986	F	Per Ilion-Repair as needed
		Ĭ								Could Not Duplicate			
12470	700	26965	3006 SPRG	7-Dec-95	N	5	24-Sep-15	24-Sep-15	Fired on Safe Release	Concern	504015	F	Per Ilion- Replace TA and tes
12466	870	25098	12 GA	15-Dec-11	N	s	24-Sep-15	24-Sep-15	Fired Out of Battery	Fired from Contact with Foreign Object	504036	F	Per Ilion- Check over completely and repair as needed at no charge
12400	870	23036	12 04	13-000-11	14	,	24-3ch-13	24-3ep-13	Fired Out of Battery	roreign object	304030		Per Ilion- Check over
12468	597	26513	22 LR	20-May-15	N	PD/S	24-Sep-15	19-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	504014	F	completely and repair as needed . Lonoke sending ammuniton (13.91
12472	DPMS A-15	N/A	223/5.56	1-Jan-15	N	s	24-Sep-15	24-Sep-15	Failed to Extract	Could Not Duplicate Concern	503930	F	Per Ilion, check over completely, repair as needed and test at no charge.
12480	870	25098	12 GA	9-May-11	N	PD/S	28-Sep-15	28-Sep-15	Fired Out of Battery	Fired from Contact with Foreign Object	504107	F	Check over completely, repair as needed, and test at no charge
12400	870	25058	12 64	5-1Vigy-11	IN	PU/S	20-369-13	20-3ep-15	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	304107	-	Replace with Ramac 85844 in
12484	710	27408	270 WIN	19-Nov-04	Y	s	28-Sep-15	28-Sep-15	Position	Concern	504038	F	exchange
12476	887	82500	12 GA	10-May-13	N	s	28-Sep-15	28-Sep-15	Jamming/Feeding	Could Not Duplicate Concern	504068	F	Per Ilion- Check over completely and repair as needed
12477	7400	24712	270 WIN	22-Oct-89	N	S	28-Sep-15	28-Sep-15	Fired while obstructed	Fired While Obstructed	504108	F	Per Ilion- Check over completely and repair as needed
46.477	7700	217.22	444	22 00105			20 309 23	20 509 25	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	304200	i	Per Ilion- Check over completely and repair as
12478	HANDI-RIFLE	72602	MARLIN	10-Feb-11	N	S	28-Sep-15	28-Sep-15	Position	Concern	504106	F	needed
12482	700	not avail.	3006 SPRG	27-Sep-72	N	PD/S	28-Sep-15	15-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504109	F	Per Ilion- Replace TA and test
			264 WIN						Delayed Firing -	Could Not Duplicate			
12483	700	not avail.	MA	15-May-70	N	S	28-Sep-15	15-Oct-15	Firearms	Concern Could Not Purellisate	504110	F	Per Ilion- Replace TA and test
12479	700	not avail.	3006 SPRG	21-Jun-84	N	5	28-Sep-15	15-Oct-15	the state of the s	Could Not Duplicate Concern	504058	F	Per Ilion- Replace TA and test
12503	700	25852	222 REM	3-Mar-93	N	5	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504188	F	Per Ilion- Replace TA and test
12498	700	not avail.	270 WIN	1-Jan-80	N	s	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504199	E	Per Ilion- Replace TA and test
44.40	700	or avail.	27.0 WHY.	2-7411-00			50-300-13	50-3cp-15	Examon	Could Not Duplicate	201222	- 1	i es more regrade un and tes
12500	700	27476	270 WIN	27-Jan-00	N	s	30-Sep-15	30-Sep-15	Fired on Safe Release	Concern	504193	F	Per Ilion- Replace TA and test

12502	700	not avail.	3006 SPRG	9-Oct-78	N	S	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	504200	F	Per Ilion- Replace TA and test
12492	700	85435	308 WIN	14-Oct-09	N	s	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504201	F	Per Ilion- Replace TA and test
12493	700	not avail.	6MM REM	1-Jan-68	N	s	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504181	F	Per Ilion- Replace TA and test
12494	700	not avail.	6MM REM	1-Jan-68	N	5	30-Sep-15	30-Sep-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504180	F	Per Ilion- Replace TA and test
12496	783	85836	3006 SPRG	22-Nov-13	N	s	30-Sep-15	30-Sep-15	Fired on Bolt Closing	Could Not Duplicate Concern	504149	F	Per Ilion- Check over completely and repair as needed
12504	1187	29825	20 GA	7-0ct-13	N	s	30-Sep-15	30-Sep-15		Could Not Duplicate Concern	504209	F	Per Ilion- Check over completely and repair as needed
12495	700	26189	22-250 REM	4-Jun-04	N	PI/S	30-Sep-15	21-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504198	F	Per Ilion- Replace TA and test, Quote for bolt & stock @ discount
12510	700	not avail.	243 WIN	28-Jun-72	N	PI/S	2-Oct-15	30-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern Could Not Duplicate	504326	F	Per Ilion- Replace TA and test
12516	700	26337	223 REM	13-Dec-07	N	5	2-Oct-15	2-Oct-15	Fired on Bolt Closing	Concern	504304	F	Per Ilion- Replace TA and test
12514	700	27474	243 WIN	2-May-02	N	s	2-Oct-15	Z-Oct-15	Other - Firearms	Could Not Duplicate Concern	504327	F	Per Ilion- Replace TA and test
12522	700	not avail.	243 WIN	23-Jan-73	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504325	F	Per Ilion- Replace TA and test
12518	700	not avail.	270 WIN	25-Oct-77	N	S	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504300	F	Per Ilion- Replace TA and test
12511	700	25931	3006 SPRG	28-Oct-94	N	s	2-Oct-15	2-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	504329	F	Per Ilion- Replace TA and test
12521	700	not avail.	3006 SPRG	28-Feb-79	N	5	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504302		Per Ilion- Replace TA and test
12519	700	not avail.	308 WIN	1-Sep-74	N	5	2-Oct-15	2-0ct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504301		Per Ilion- Replace TA and test
12517	700	26273	375 RUM	11-Jul-01	N	s	2-Oct-15	2-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504324		Per Ilion- Replace TA and test
12512	870	not avail.	12 ga	1-Jul-13	N	s	2-Oct-15	2-Oct-15	Fired Out of Battery	Fired from Contact with Foreign Object	504324	F	Per Ilion- Check over completely
12515	887	82500	12 GA	22-Jun-12	N	s	2-Oct-15	2-Oct-15	Fired With Safe ON	Could Not Duplicate Concern	504322	F	Per Ilion- Check over completely and repair as needed

													Per Ilion- Check over
12513	1187	83617	12 GA	5-Jun-12	N	S	2-Oct-15	2-Oct-15	Other - Firearms	Sent in for Evaluation	504285	F	completely
12531	770	85634	308 WIN	14-Mar-11	Υ	PI/S	5-Oct-15		Fired on Bolt Closing	Other - Unexamined		F	
12530	597	26550	22 LR	8-Jan-13	N	s	7-Oct-15	7-Oct-15	Defective Parts	Could Not Duplicate Concern	504457		Per Ilion- Repair as needed
12539	597	26537	22 LR	6-Aug-13	N	s	7-Oct-15	7-Oct-15	Fired Out of Battery	Other - Unspecified or Undetermined - Ammunition	504482	F	Per Ilion- Check over
12533	700	not avail.	270 WIN	27-Jun-80	N	s	7-Oct-15	7-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504444	F	Per Ilion- Replace TA and tes
aurita is	ACCUPACION .		300 WIN	DESCRIPTION OF THE PARTY OF THE	045.50				NAME OF THE PARTY	Could Not Duplicate	NAMES AND STREET		
12538	700	84526	MA	15-Jul-15	N	S	7-Oct-15	7-Oct-15	Fired on Bolt Closing	Concern Could Not Dunition	504493	F	Per Ilion- Replace TA and bo
12537	700	not avail.	3006 SPRG	4-Dec-80	N	s	7-Oct-15	7-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504492	F	Per Ilion- Replace TA and tes
12532	700	not avail.	7MM REM MA	1-Aug-67	N	S	7-Oct-15	7-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504443		Per Ilion- Replace TA and tes
12536	700	25933	7MM REM MA	15-Aug-00	N	5	7-0ct-15	7-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504510	F	Per Ilion- Replace TA and tes
	770	00000	3005 5005		0.7				F	Could Not Duplicate	******		D. W
12535	770	85656	3006 SPRG	24-Feb-09	Υ	5	7-Oct-15	7-Oct-15	Fired on Bolt Closing	Concern	504524	F	Per Ilion- Replace TA and tes Consumer Service replaced
12529	CARBON 15	91037	223/5.56	12-May-14	N	PD/S	7-Oct-15	7-Oct-15	My Gun Blew Up	Wrong Ammunition Fired in Gun Could Not Duplicate	504445	F	with Ramac 90289 in exchange Replace with Ramac 85842 in
12552	770	85637	243 WIN	4-Oct-13	Υ	PI/S	8-Oct-15	19-Nov-15	Bullet Fragmented	Concern	505699	F	
										Other - Unspecified or Undetermined -			Per Ilion-Replace with XT17
12550	597	26516	17 HMR	14-Mar-05	N	PD/S	9-Oct-15	9-Oct-15	My Gun Blew Up	Ammunition	504583	F	at n/c
12546	710	27410	3006 SPRG	1-Aug-03	Y	PD/S	9-Oct-15	9-Oct-15	Ammunition Exploded	Over pressured shell Could Not Duplicate	504533	F	Consumer Service replaced with Ramac 85846 in exchange
12548	700	27093	243 WIN	23-Jun-08	N	S	9-Oct-15	9-Oct-15	Fired With Safe ON	Concern	504610	F	Per Ilion- Replace TA and tes
12551	700	not avail.	243 WIN	9-Dec-77	N	s	9-Oct-15	9-Oct-15	Fired on Safe Release	Could Not Duplicate Concern	504612	F	Per Ilion- Replace TA and tes
12545	700	25709	308 WIN	4-Apr-14	N	s	9-Oct-15	9-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	504643	F	Per Ilion- Replace TA and tes
	10.200.000	(150) 150(10)			155		***********		Unexplained	620 0750 020 0 4 500 V +600 V			Per Ilion- Replace TA and bol
12544	770	85653	3006 SPRG	26-Jun-08	Y	S	9-Oct-15	9-Oct-15	Discharge Safe OFF	Sent in for Evaluation	504645	F	and test
12549	CARBON 15	90689	223/5.56	2-Apr-13	N	PD/S	9-Oct-15	9-0ct-15	My Gun Blew Up Unexplained	Over pressured shell	504559	F	Replace with Ramac 90289 i exchange
12556	700	27474	243 WIN	9-Oct-98	N	S	13-Oct-15	13-Oct-15	Discharge - No Mention of Safety Position	Altered Adjustments or Components	504701	F	Per Ilion- Replace TA and tes
12554	700	not avail.	300 WIN	9-Oct-78	N	S	13-Oct-15	13-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504733	F	Per Ilion- Replace TA and tes
12557	700	25775	308 WIN	17-Mar-95	N	s	13-Oct-15	13-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504732	F	Per Ilion- Replace TA and tes

		1				100				Altered Adjustments or			
12555	700	not avail.	6MM REM	1-Mar-67	N	S	13-Oct-15	13-Oct-15	Fired on Safe Release	Components	504691	F	Per Ilion- Replace TA and tes
12558	770	85637	243 WIN	20-Feb-08	Υ	s	13-Oct-15	13-Oct-15	Ammunition Exploded	Over pressured shell	504690	F	Per Ilion- Check over completely
						- 3							Per Ilion-Replace action and
12563	700	27389	300 RUM	11-Jun-15	N	PD/S	16-Oct-15	16-Oct-15	Broken Part	Sent in for Evaluation	504919	F	test
12562	700	not avail.	270 WIN	20-Jul-78	N	s	16-Oct-15	16-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	504855	F	Per Ilion- Replace TA and tes
12565	700	not avail.	270 WIN	19-Jul-76	N	s	16-Oct-15	16-Oct-15	Unexplained Discharge Safe OFF	Altered Adjustments or Components	504832	F	Per Ilion- Replace TA and tes
12561	700	not avail.	6MM REM	16-Feb-72	N	s	16-Oct-15	16-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504854	F	Per Ilion- Replace TA and tes
12572	700	not avail.	243 WIN	24-Feb-78	N	s	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505035	F	Per Ilion- Replace TA and tes
12577	700	not avail.	270 WIN	1-May-76	N	s	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	505032		Per Ilion- Replace TA and tes
123//	700	not avail.	270 99119	1-ividy-70	14	3	20-001-13	20-001-13	Position	Could Not Duplicate	303032	- 1	rei illon- neplace IA and tes
12574	700	not avail.	3006 5PRG	1-Jun-78	N	5	20-Oct-15	20-Oct-15	Fired on Safe Release	Concern	505037	F	Per Ilion- Replace TA and tes
12575	700	not avail.	3006 SPRG	12-Oct-72	N	S	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	505034	F	Per Ilion- Replace TA and tes
12578	700	27095	3006 SPRG	19-Oct-12	N	s	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	504940	F	Per Ilion- Replace TA and tes
12573	700	not avail.	7MM REM MA	1-Sep-63	N	s	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	505036	F	Per Ilion- Replace TA and tes
			7MM REM						Unexplained Discharge - No Mention of Safety	Altered Adjustments or			
12580	700	not avail.	MA	1-Mar-68	N.	S	20-Oct-15	20-Oct-15	Position	Components	505031	F	Per Ilion- Replace TA and tes
12579	770	85632	270 WIN	27-Mar-07	Y	s	20-Oct-15	20-Oct-15	Fired on Bolt Opening	Sent in for Evaluation	504941	F	Per Ilion- Check over completely
12576	SEVEN	not avail.	7MM-08 REM	1-Mar-94	N	s	20-Oct-15	20-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	505033	F	Per Ilion- Replace TA and tes
					-	-					203000	T,	Per Ilion- Check over
12588	700	84344	220 SWIFT	17-Jul-13	N	PD/S	22-Oct-15	22-Oct-15	Ammunition Exploded	Sent in for Evaluation Not Examined by Product	505117	F	completely and repair as needed Rifle not returned to Ilion fo
12589	700	84203	308 WIN	31-May-13	N	5	23-Oct-15	4-May-16	Fired on Bolt Closing	Service	n/a	F	exam
F 2 3 7 1 2 1		2000000	25.000.0000						522-000-000				Check over completely, repair as needed, and test at no
12593	700	84207	308 WIN	12-Jun-09	N	PI/PD/S	26-Oct-15	26-Oct-15	Case Failure	Sent in for Evaluation	505094	F	charge
12597	700	not avail.	243 WIN	22-Oct-76	N	s	26-Oct-15	28-Oct-15	Fired on Safe Release	Sent in for Evaluation	505142	F	Per Ilion- Replace TA and tes

_					_							_	
12600	700	not avail.	3006 SPRG	13-Oct-69	N	s	26-Oct-15	26-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505245	F	Per Ilion- Replace TA and test
			7MM REM				new terror and			Section Control of the Control of			
12598	700	not avail.	7MM REM	1-Aug-74	N	S	26-Oct-15	28-Oct-15	Fired With Safe ON Unexplained	Sent in for Evaluation Could Not Duplicate	505140	F	Per Ilion- Replace TA and test
12599	700	not avail.	MA	15-Jul-83	N	5	26-Oct-15	26-Oct-15	Discharge Safe ON	Concern	505228	F	Per Ilion- Replace TA and test
	7,44		7MM REM							Altered Adjustments or		Ť	
12601	700	not avail.	MA	22-Mar-72	N.	S	26-Oct-15	28-Oct-15	Fired on Bolt Closing	Components	505246	F	Per Ilion- Replace TA and test
12596	870	81214	12 GA	4-Sep-13	N	s	26-Oct-15	26-Oct-15	Fired on Bolt Closing	Could Not Duplicate Concern	505114	F	Per Ilion- Check over completely
02.220	950000	100,200	7MM-08	50.17 (38)		-		2002000		Could Not Duplicate	12/25/01		
12594	SEVEN	24786	REM	14-Apr-90	N	S	26-Oct-15	28-Oct-15	Fired on Bolt Closing	Concern Fired from Contact with	505141	F	Per Ilion- Replace TA and test Replace with Ramac 81049 in
12602	1187	27081	12 GA	24-May-07	N	PD/S	26-Oct-15	5-Nov-15	My Gun Blew Up	Foreign Object	505239	F	
12595	CARBON 15	91036	223/5.56	14-Apr-14	Y	PD/S	26-Oct-15	5-Jan-16	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505143	F	Per Ilion- Replace at no charge
12604	700	25767	243 WIN	15-Aug-90	N	PI/S	27-Oct-15	18-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505303		Per Ilion- Replace TA and test
22001	700	23707	L. S. Jillie	as riag so		1.05	27 001 25	10 (101 15	T.O.J.D.O.F	Could Not Duplicate	303303	+	Ter mon inspace in one ies
12607	700	25773	3006 SPRG	27-Nov-01	N	S	29-Oct-15	29-Oct-15	Fired on Safe Release	Concern	505465	F	Per Ilion- Replace TA and test
12608	700	25634	3006 SPRG	14-Oct-93	N	S	29-Oct-15	29-Oct-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505302	F	Per Ilion- Replace TA and test
12606	700	not avail.	7MM REM MA	12-Aug-69	N	s	29-Oct-15	29-Oct-15	Fired on Safe Release	Improper Maintenance	505297		Per Ilion- Replace TA and test
12609	VERSA MAX	81048	12 GA	2-Mar-12	N	PI/S	29-Oct-15	9-Nov-15	Broken Part	Could Not Duplicate Concern	505458	F	Repair @ n/c - goodwill
12605	597	80850	22 LR	9-Jul-07	N	s	29-Oct-15	5-Nov-15	Went Automatic	Could Not Duplicate Concern	505296	F	Check over completely, repair as needed, and test at no charge
12610	SEVEN	29551	7MM SAUM	31-Jan-03	N	s	29-Oct-15	9-Nov-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	505463	F	Per Ilion- Replace TA and test
12611	DPMS A-15	60531	5.56	10-Apr-15	N	PD/S	29-Oct-15	29-Oct-15	Unknown Claim	Over pressured shell	505464	F	Replace with Ramac 60531 in exchange at a 50% discount
12617	700	27255	300 WSM	7-Feb-09	N	s	2-Nov-15	7-Dec-15	Fired on Safe Release	Other - Unexamined	See Case 12729	F	See Case 12729
new coc	S (1940,000)		200000000000000000000000000000000000000	5000000-00 6 00 AM					Unexplained Discharge - No Mention of Safety	Could Not Duplicate	- 1501 GASAGAS		
12625	770	85633	3006 SPRG	19-Mar-07	Y	PI/PD/S	3-Nov-15	13-Nov-15	Position Unexplained Discharge - No	Concern	505528	F	Per Ilion- Replace TA and test
12628	700	85435	308 WIN	8-Dec-10	N	PI/S	3-Nov-15	3-Nov-15	Mention of Safety Position	Could Not Duplicate Concern	505595	F	Per Ilion- Replace TA and test
32020	700	03433	300 1111	5-000-10	100	rijs	J-110V-13	2-HOV-13	Unexplained	Content	30333	+	i sa mont neproce is and test
									Discharge - No Mention of Safety	Could Not Duplicate			
12621	700	not avail.	25-06 REM	22-Feb-71	N	S	3-Nov-15	3-Nov-15	Position	Concern	505596	F	Per Ilion- Replace TA and test
12629	700	not avail.	270 WIN	27-Apr-73	N	s	3-Nov-15	3-Nov-15	Fired on Bolt Closing	Altered Adjustments or Components	505598	F	Per Ilion- Replace TA and test
12631	700	27476	270 WIN	17-Jun-03	N	s	3-Nov-15	3-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505594	F	Per Ilion- Replace TA and test

12632	700	25773	3006 SPRG	11-Apr-89	N	s	3-Nov-15	3-Nov-15	Fired on Bolt Closing	Could Not Duplicate Concern	505597		Per Ilion- Replace TA and test
0.000	120000	91 (04)	50542159030	contract State	200	-	SAME END	1975227 1270	ISM OF VERNINA	Altered Adjustments or	SALAR		
12626	700	not avail.	308 WIN	1-Aug-62	N	S	3-Nov-15	3-Nov-15	Fired on Safe Release	Components	505529	F	Per Ilion- Replace TA and tes
12624	700	not avail.	7MM REM MA	1-Apr-83	N	s	3-Nov-15	3-Nov-15	Fired on Safe Release	Altered Adjustments or Components	505531	F	Per Ilion- Replace TA and tes
12630	700 ML	27572	50 CAL	7-Nov-96	N	s	3-Nov-15	3-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505569		Per Ilion- Replace TA and tes
12030	700 1112	2/3/2	JO CAL	7-1404-30		-	3-1404-13	3-1404-13	THEO OF SOIL NEIGOSE	Concern	303303	+	CSR in the Call Center
12620	Excel Auto	72350	12 GA	7-Sep-13	Y	s	3-Nov-15	4-Dec-15	Fired With Safe ON	Sent in for Evaluation	505532	F	replaced shotgun through
									Barrel Burst/Split (Other than				Per Ilion, replace in exchange with Ramac 85847 at no
12637	783	85837	308 WIN	19-Sep-13	N	PD/S	5-Nov-15	5-Nov-15	Chamber)	Fired While Obstructed	505657	F	
				25 0 0 p 20		1.070		2		Could Not Duplicate		1	
12634	700	27011	270 WIN	1-Sep-06	N	s	5-Nov-15	5-Nov-15	Fired on Safe Release	Concern	505604	F	Per Ilion- Replace TA and test
										Could Not Duplicate			
12635	700	29663	308 WIN	21-Oct-09	N	S	5-Nov-15	5-Nov-15	Fired on Safe Release	Concern	505659	F	Per Ilion- Replace TA and test
			7MM REM			- 2			45-07. 40 MMT/G	Could Not Duplicate			
12638	700	not avail.	MA	6-Jun-73	N	S	5-Nov-15	5-Nov-15	Fired on Bolt Closing	Concern	505621	F	Per Ilion- Replace TA and test
12636	870	25561	20 GA	9-Dec-14	N	s	5-Nov-15	5-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505660	F	Per Ilion- Check over completely and repair as needed
													Per Ilion- Check over
0.000000			4,47539000	resource/res		200			Participal Constant	ACCUSATE DESCRIPTION		100	completely and repair as
12640	Handi-Rifle	72530	280 REM	15-Jul-09	N	5	5-Nov-15	5-Nov-15	Case Separation	Sent in for Evaluation	505669	F	needed
20000									Unexplained Discharge - No Mention of Safety				
12648	700	not avail.	243 WIN	26-Jun-75	N	S	9-Nov-15	9-Nov-15	Position	AFT MKT TRIGGER ASSM	505780	F	Per Ilion- Replace TA and test
12642	700	not avail.	270 WIN	20-Sep-71	N	s	9-Nov-15	9-Nov-15	Fired on Bolt Closing	Improper Maintenance	505776	F	Per Ilion- Replace TA and test
12644	700	not avail.	270 WIN	19-Jul-78	N	s	9-Nov-15	9-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505772	F	Per Ilion- Replace TA and test
12643	700	27535	300 WIN	5-Jan-99	N	s	9-Nov-15	9-Nov-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or	505778		Per Ilion- Replace TA and test
12643	700	2/535	IVIA	2-19U-99	14	2	3-MOA-12	3-MOA-12	Position	Components Could Not Duplicate	505778	- 1	Per Illon- Keplace IA and test
12641	770	85649	243 WIN	1-Jul-13	Y	S	9-Nov-15	9-Nov-15	Fired on Bolt Closing	Concern	505774		Per Ilion- Replace TA and test
										Could Not Duplicate			Per Ilion- Check over completely and repair as
12645	7400	29769	3006 SPRG	22-Mar-96	N	S	9-Nov-15	9-Nov-15	Went Automatic	Concern	505777	F	
										Could Not Dunliest			Check over completely, repair
12649	700	N/A	270 WIN	12-Jan-72	N	PI/PD/S	9-Nov-15	16-Dec-15	Fired With Safe ON	Could Not Duplicate Concern	507074	F	as needed, and test at no charge
12649	700	N/A	270 WIN	12°/an°/2	IN	PI/PU/S	3-NOV-15	10-000-15	Fired With Sale ON	Concern	50/0/4	- 1	Replace with Ramac 90289 in
12646	CARBON 15	90689	5.56	17-Jul-12	N	PD/S	9-Nov-15	9-Nov-15	My Gun Blew Up	Case Separation	505741	F	exchange
12647	552	25594	22 RF	5-Aug-14	N	s	9-Nov-15	27-Jan-16	Fired Out of Battery	Could Not Duplicate Concern	507941	F	Per Release - Check for \$607.45 (refund of firearm & shipping)
1704/	222	25594	22 10	5-Aug-14	IN	3	3-MOV-15	z/-Jan-16	rired Out of Battery	Other - Unspecified or	50/941	+	snipping
12651	700	84342	22-250 REM	2-Apr-15	N	PD/S	10-Nov-15	10-Nov-15	Broken Part	Undetermined - Ammunition	505844	F	Per Ilion- Check over completely
12654	770	85634	308 WIN	8-Nov-12	Y	PD/S	10-Nov-15	10-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505863	F	Per Ilion- Check over completely

12655	700	25787	243 WIN	13-Feb-86	N	s	10-Nov-15	10-Nov-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	505848	F	Per Ilion- Check over completely
12652	700	25791	270 WIN	21-Oct-88	N	5	10-Nov-15	10-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505866	F	Per Ilion- Replace TA and test
12653	700	not avail.	3006 SPRG	3-Apr-69	N	5	10-Nov-15	10-Nov-15	Fired With Safe ON	Could Not Duplicate Concern	505795		Per Ilion- Replace TA and test
12657	VERSA MAX	83500	12 GA	23-Sep-15	N	S	10-Nov-15	10-Nov-15	Fired on Safe Release	Could Not Duplicate Concern	505843	F	Per Ilion- Check over completely
12660	710	27412	7MM MAG	10-Feb-06	Υ	S/C	12-Nov-15	18-Dec-15	Jamming/Feeding issues	Sent in for Evaluation	507061	F	Replace w/85848 in exchange through SNC order
12667	597	26516	17 HMR	13-Jun-03	N	PD/S	13-Nov-15	19-Nov-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	505875	F	Converting to 22 WMR as requested by customer
12664	700	84600	223 REM	8-Jan-13	N	s	13-Nov-15	13-Nov-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	505950	F	Per Ilion- Check over completely and repair as needed
12665	700	85508	300 WIN		N	5	13-Nov-15	13-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505980	F	Per Ilion- Replace TA and test
12662	700	84207	308 WIN	16-Jan-09	N	S	13-Nov-15	19-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	505981	F	Repair @ n/c under XMP recall
12666	700	29663	308 WIN	11-Oct-07	N	s	13-Nov-15	13-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	505979	E	Per Ilion- Replace TA and test
12663	XM15-E2S	90391	223/5.56	4-Oct-13	N	PD/S		13-Nov-15	My Gun Biew Up	Other - Unspecified or Undetermined - Ammunition	505935	F	Check over completely, repair as needed, and test at a 50% discount
12678	1100	not avail.	12 GA	1-Aug-85	N	PD/S	17-Nov-15	17-Nov-15	Ammunition Exploded	Other - Unspecified or Undetermined - Ammunition	506097	F	Per Ilion- Check over completely
12679	700	not avail.	270 WIN	17-Dec-69	N	S	17-Nov-15	17-Nov-15		Could Not Duplicate Concern	506054	F	Per Ilion- Replace TA and test
12684	700	not avail.	270 WIN	19-Jan-72	N	S	17-Nov-15	23-Nov-15	Other - Firearms - XMP Update	Could Not Duplicate Concern	506094	F	Per Ilion- Replace TA and test
12680	700	25807	300 WIN MA	1-Mar-05	N	S	17-Nov-15	17-Nov-15	Fired on Safe Release	Could Not Duplicate Concern Could Not Duplicate	506098	F	Per Ilion- Replace TA and test
12683	700	not avail.	3006 SPRG 7MM REM	30-May-80	N	S	17-Nov-15	17-Nov-15	Fired on Bolt Closing	Concern Could Not Duplicate	506051	F	Per Ilion- Replace TA and test
12682	700	25803	MA	10-Apr-02	N	S	17-Nov-15	20-Nov-15	Fired on Bolt Closing	Concern Altered Adjustments or	506093	F	Per Ilion- Replace TA and test
12685	722	not avail.	222 REM	1-Jun-57	Υ	S	17-Nov-15	30-Nov-15	Fired on Safe Release	Components Could Not Duplicate	506049	F	Per Ilion- Replace TA and test
12681	700	not avail.	3006 SPRG	11-Feb-77	N	PD/S	17-Nov-15	4-Dec-15	Fired on Bolt Closing Barrel Burst/Split (Other than	Concern	506118		Replace TA @ n/c - goodwill Per Ilion - Quote to repair @
12700	700	84275 25568	3006 SPRG	17-Oct-14	N	PD/S		20-Nov-15	Chamber) Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	506285	F	Per Ilion, replace in exchange with Ramac 25568 at 50% discount.

12692	1187	26920	20 GA	31-Jan-06	N	PD/S	20-Nov-15	20-Nov-15	My Gun Blew Up	Slow to Peak	506257	F	Per Ilion, check over completely, repair as needed and test at no charge.
12690	7400	29767	308 WIN	15-Jan-93	Y	PD/S	20-Nov-15	20-Nov-15	Barrel Burst/Split (Other than Chamber)	Fired While Obstructed	506191	F	Per Ilion, check over completely, repair as needed and test at a 50% discount.
12694	700	not avail.	270 WIN	7-Oct-76	N	PI/S	20-Nov-15	20-Nov-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	506241	F	Per Ilion, check over completely, repair as needed and test at no charge.
12693	673	24687	350 REM MA	3-Jul-03	N	s	20-Nov-15	20-Nov-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506174	F	Per Ilion, check over completely, repair as needed and test at no charge.
	100000		0.000/00000	ESTEROTORY C		39	MODERN CONTRACT	STATE OF STA		Could Not Duplicate		1.0	Per Ilion replace trigger at ne
12697	700	85206	270 WIN	7-Jan-14 29-Feb-72	N	S		20-Nov-15	Fired With Safe ON Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	506168	F	Per Ilion - Replace TA & test
12691	770	85649	243 WIN	21-Nov-12	Y	5			Fired on Safe Release	Could Not Duplicate Concern	506219	F	Per Ilion, check over completely, repair as needed
12696	SPORTSMAN 78 H&R HANDI RIFLE	not avail.	308 WIN	17-Sep-88	N Y	S PI/S		20-Nov-15	Unexplained Discharge - No Mention of Safety Position Ammunition Exploded	Could Not Duplicate Concern Other - Unspecified or Undetermined - Ammunition	506242	F	Per Ilion, check over completely, repair as needed and test at no charge. Per Release - Replace w/27355 in exchange
12704	700	N/A	3006 SPRG	19-Feb-82	N	s s	12000 200	ABA F	Exploded Fired on Bolt Closing	Could Not Duplicate Concern	507531	F	Per Ilion, check over completely, repair as needed
12705	700	25798	223 REM	25-Jan-86	N	5	30-Nov-15	9-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506441	F	Per Ilion - Replace TA & test
12709	700	not avail.	3006 SPRG	6-Jul-71	N	s	30-Nov-15	9-Dec-15	Fired on Bolt Closing	Altered Adjustments or Components	506408	F	Per Ilion - Replace TA & test @ n/c
12710	700	25759	6.5 X 55 S	5-Jan-94	N	s	30-Nov-15	8-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	506175	F	Per Ilion - Replace TA & test
									Unexplained Discharge - No Mention of Safety	Could Not Duplicate			
12714	770	85632	270 WIN 7MM-08	4-Jan-11	Υ	S	30-Nov-15	4-Dec-15	Position	Concern Altered Adjustments or	506376	F	Per Ilion - Repair at n/c Per Ilion - Replace TA & test
12712	SEVEN	24741	REM	4-May-98	N	s	30-Nov-15	16-Dec-15	Fired on Safe Release	Components	506405	F	@ n/c - goodwill
12713	700	N/A	243 WIN	8-Mar-83	N	S	30-Nov-15	30-Nov-15	Delayed Firing - Firearms	Could Not Duplicate Concern	506307	F	Per Ilion, check over completely, repair as needed and test at no charge
12726	700	25767	243 WIN	3-Apr-85	N	s	2-Dec-15	2-Dec-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	506561	F	Per Ilion, replace trigger assembly, check over at no charge

12716	700	27095	3006 SPRG	9-Oct-12	N	5	2-Dec-15	2-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	506467	F	Per Ilion, replace trigger assembly, check over at no charge
										Could Not Duplicate			Per Ilion - Repair at n/c, XMF
12722	700	27196	3006 SPRG	14-Jun-10	N	S	2-Dec-15	9-Dec-15	Fired on Safe Release	Concern	506609	F	update
12717	887	82502	12 GA	28-Mar-14	N	S	2-Dec-15	7-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	506460	F	Refund check \$520
12734	700	25771	270 WIN	28-Sep-95	N	S	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506621	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12733	700	25735	300 RUM	24-Jul-00	N	S	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	506619	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12729	700	27255	300 WSM	7-Feb-09	N	s	3-Dec-15	3-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506565	F	Per Ilion - Replace TA & test @ n/c
12738	700	27478	3006 SPRG	19-Aug-98	N	5	3-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	506748	F	Per Ilion - Replace TA & test
12731	700	26917	308 WIN	16-Nov-95	N	5	3-Dec-15	3-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506620	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12736	700	not avail.	308 WIN	5-Jul-72	N	s	3-Dec-15	10-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	506583	F	Per Ilion - Replace TA & test @ n/c
12730	770	85648	300 WIN	27-May-09	Y	5	3-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506558	F	Per Ilion - Replace TA & test
	78								Unexplained Discharge - No Mention of Safety	Could Not Duplicate			Per Ilion, replace trigger assembly, check over, and
12732	Sportsman Savage AXIS	26164 n/a	3006 SPRG 7MM MAG	22-Jul-87	Y	S PI/PD/S	3-Dec-15 4-Dec-15	3-Dec-15 5-Apr-16	Position Ammunition Mixed in Box	Concern Other - Unspecified or Undetermined - Ammunition	506584 n/a	F	Per Release - Replace w/84163 in exchange
12752	700	27490	223 REM	7-Feb-95	N	s	8-Dec-15	8-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	506747	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12748	700	not avail.	270 WIN	21-May-75	N	s	8-Dec-15	11-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506746	F	Per Ilion - Replace TA & test @ n/c
12749	700	25632	280 REM	13-Mar-86	N	5	8-Dec-15	8-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506679	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12750	700 ML	27572	50 CAL	28-Aug-96	N	s	8-Dec-15	8-Dec-15	Unexplained Discharge - No Mention of Safety Position	Sent in for Evaluation	506749	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12756	660	N/A	243 WIN	1-Jul-67	Y	S	9-Dec-15	9-Dec-15	Other - Firearms	Altered Adjustments or Components	506930	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12759	700	25614	243 WIN	16-Aug-89	N	S	9-Dec-15	9-Dec-15	Fired With Safe ON	Altered Adjustments or Components	506928	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12760	700	N/A	270 WIN	12-Sep-73	N	5	9-Dec-15	9-Dec-15	Unexplained Discharge - No Mention of Safety Position	AFT MKT TRIGGER ASSM	506926	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge

12761	700	N/A	3006 SPRG	30-Jan-73	N	S	9-Dec-15	9-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	506922	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
										Could Not Duplicate			Per Ilion, replace trigger assembly, check over, and
12758	Excel Auto	72350	12 GA	20-May-14	Υ	5	9-Dec-15	9-Dec-15	Fired on Safe Release	Concern	506924	F	test fire at no charge
12757	SEVEN	29555	300 SAUM	7-May-03	N	S	9-Dec-15	9-Dec-15	Fired on Safe Release	Altered Adjustments or Components	506929	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12766	700	25773	270 WIN	13-Jan-94	N	5	10-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506925	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12767	700	N/A	7MM REM MA	21-Sep-77	N	S	10-Dec-15	10-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	506932	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12776	Axis	N/a	30/06		N	PD/S	11-Dec-15	22-Dec-15	Wrong Ammunition Fired in Gun	Wrong Ammunition Fired in Gun	n/a	A	Lonoke to cover costs (\$350)
13900	997	97540	12.64	25 Apr. 14	M	DO/F	14 Doc 15	20. Dec 15	Elead With Safe Chi	Could Not Duplicate	507100		Check over completely, repair as needed, and test at no
12800	887	82540	12 GA	25-Apr-14	N	PD/S		30-Dec-15	Fired With Safe ON Unexplained Discharge - No Mention of Safety	Concern Could Not Duplicate	507109	F	charge Per Ilion - Replace TA & test
12786	700	not avail.	3006 SPRG	1-Jul-71	N	PI/S	14-Dec-15	16-Dec-15	Position	Concern	507060	F	@ n/c
12799	700	not avail.	270 WIN	2-Feb-79	N	5	14-Dec-15	18-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507131	F	Per Ilion - Replace TA & test @ n/c
22/22	700	not avail.	300 WIN	246073		,	14-00-13	10-000-15	Unexplained Discharge - No Mention of Safety	Concern	307131		Per Ilion, replace trigger assembly, check over, and
12802	700	N/A	MA	21-Oct-79	N	S	14-Dec-15	14-Dec-15	Position	Improper Maintenance	507129	F	test fire at no charge
12801	700	27255	300 WSM	16-Nov-06	N	s	14-Dec-15	18-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507248	F	Per Ilion - Replace TA & test @ n/c
12789	700	26035	3006 SPRG	21-Jan-98	N	S	14-Dec-15	14-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	507068	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12791	700	not avail.	3006 SPRG	21-Mar-83	N	5	14-Dec-15	17-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507062	F	Per Ilion - Replace TA & test
12794	700	25773	3006 SPRG	14-Aug-97	N	S	14-Dec-15	14-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	507132	F	Per Ilion, replace trigger assembly at no charge, replace bolt at 25% discount
and the same of	,,,,,	22.12	230031110	-11106 31					7.0311011	Could Not Duplicate	207.200	-11	Per Ilion - Replace TA & test
12796	700	not avail.	3006 SPRG	13-Nov-69	N	S	14-Dec-15	18-Dec-15	Fired on Safe Release Other - Firearms -	Concern Could Not Duplicate	507130	F	@ n/c
12797	700	84467	308 WIN	31-Jul-09	N	5	14-Dec-15	17-Dec-15	XMP Update	Concern	507111	F	Per Ilion - Replace TA @ n/c
12793	700	N/A	7MM REM MA	2-Jun-72	N	5	14-Dec-15	14-Dec-15	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	507059	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12785	788	N/A	30-30 WIN		Y	s			Fired on Bolt Closing	Could Not Duplicate Concern	507073		Per Ilion, check over completely, repair as needed, and test at no charge as a goodwill gesture

		_			-					Altered Adjustments or			
12787	R-25	60030	243 WIN	17-Oct-14	N	s	14-Dec-15	17-Dec-15	Fired on Safe Release	Components	507065	F	Per Ilion - Quote to repair
12/0/	N-23	60030	245 WIIV	17-001-14	14	3	14-060-15	17-060-15	Unexplained Discharge - No	Dec 21 Indicate Anni Anni Anni Anni Anni Anni Anni Ann	307003	ľ	Check over completely, repa
12804	1187	83680	12 GA	29-Oct-07	N	PD/S	14-Dec-15	15-Jan-16	Mention of Safety Position	Could Not Duplicate Concern	508265	F	as needed, and test at no charge
17017	700	26109	17 REM	20-Jan-00	N	s	16 Dec 15	13 ton 15	Fined on Bolt Clasins	Could Not Duplicate	503363	F	Per Ilion - Replace TA & tes
12813	700	20109	17 KEIVI	20-Jan-00	IV	3	16-Dec-15	13-Jan-16	Fired on Bolt Closing	Concern Could Not Duplicate	507367	- 1	@ n/c Per Ilion - Replace TA & tes
12819	700	27478	3006 SPRG	31-Aug-95	N.	S	16-Dec-15	12-Jan-16	Fired on Bolt Closing Unexplained	Concern	507394	F	@ n/c
			7MM REM	(-180e) - 190					Discharge - No Mention of Safety	Could Not Duplicate			Per Ilion - Replace TA & tes
12816	700	27480	MA	17-Nov-99	N	S	16-Dec-15	25-Jan-16	Position	Concern	507395	F	@ n/c
12817	700	not avail.	7MM REM MA	1-Apr-67	N	s	16-Dec-15	12-Jan-16	Delayed Firing - Firearms	Could Not Duplicate Concern	507393	F	Per Ilion - Replace TA & test @ n/c
									Delayed Firing -	Could Not Duplicate			7.3
12815	710	27410	3006 SPRG	28-Jul-03	Υ	S	16-Dec-15	13-Jan-16	Firearms	Concern Could Not Duplicate	507352	F	Replace w/85846 in exchang Per Ilion - Replace TA & test
12821	700	not avail.	270 WIN	13-Apr-82	N	s	17-Dec-15	11-Jan-16	Fired on Bolt Closing	Concern	507368	F	@ n/c
12844	700 ML	27580	50 CAL	23-Jul-97	N	PD/S	22-Dec-15	22-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507790	F	Per Ilion - Replace TA & test @ n/c
12839	700	not avail.	270 WIN	14	N	S	22-Dec-15	110000000000000000000000000000000000000	Fired on Safe Release	Could Not Duplicate Concern	A CONTRACTOR	F	Per Ilion - Replace TA & test @ n/c
12839	700	not avail.	270 99119	1-Aug-66	IV	3	22-Dec-15	28-Dec-15	Fired on Bolt	Could Not Duplicate	507799	F	Per Ilion - Replace TA & test
12824	700	not avail.	3006 SPRG	1-Jun-67	N	s	22-Dec-15	22-Dec-15	Opening	Concern	507500	F	@ n/c
12830	700	not avail.	308 WIN	16-Jul-71	N	s	22-Dec-15	28-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	507536	F	Per Ilion - Replace TA & test @ n/c
12829	700	not avail.	6MM REM	10-Nov-76	N	s	22-Dec-15	78-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507547	F	Per Ilion - Replace TA & test @ n/c
												T	Per Ilion - Replace TA & test
12826	721	not avail.	3006SPRG	1-Jan-64	Y	S	22-Dec-15	22-Dec-15	Fired on Bolt Closing	Sent in for Evaluation	507540	F	@ n/c Per Ilion, replace trigger
			7MM REM							Could Not Duplicate	- Anna Anna Anna Anna Anna Anna Anna Ann		assembly, check over, and
12843	770	85654	MA	31-Mar-09	Υ	S	22-Dec-15	22-Dec-15	Fired on Safe Release Unexplained	Concern	507800	F	test fire at no charge
									Discharge - No Mention of Safety	Could Not Duplicate			Per Ilion - Replace TA & test
12831	700	25773	3006 SPRG	31-Aug-95	N	S	22-Dec-15	25-Jan-16	Position	Concern	507537	F	@ n/c
12836	700	not avail.	3006 SPRG	26-Oct-71	N	s	22-Dec-15	14-Jan-16	Fired on Safe Release	Altered Adjustments or Components	507541	F	Per Ilion - Replace TA & test @ n/c
12832	700	85435	308 WIN	31-Jan-11	N	5	22-Dec-15	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507539	F	Per Ilion - Replace TA & test @ n/c
12828	700	not avail.	6MM REM	17-Aug-70	N	s	22-Dec-15	27-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507535	F	Per Ilion - Replace TA & test @ n/c
12835	700	not avail.	7MM REM MA	9-Jan-73	N	5	22-Dec-15	14-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507532	F	Per Ilion - Replace TA & test @ n/c
			****			-				Altered Adjustments or			Replace w/ramac 85844 in
12842	710	27408	270 WIN	10-Nov-05	N	S	22-Dec-15	11-Jan-16	Fired on Safe Release Unexplained Discharge - No Mention of Safety	Components	507796	F	exchange
12827	710	27410	3006 SPRG	7-Feb-05	Y	s	22-Dec-15	28-Jan-16	Position	Sent in for Evaluation	507533	F	Replace w/85846 in exchang
										Could Not Duplicate			Per Ilion - Replace TA & test

12849	597	26513	22 LR	14-Nov-14	N	S	23-Dec-15	23-Dec-15	Went Automatic	Could Not Duplicate	507682	F	Per Ilion, check over completely, repair as needed and test at no charge
12851	700	N/A	3006 SPRG	27-Jul-72	N	PD/S	28-Dec-15	5-Feb-16	Fired on Safe Release	Altered Adjustments or Components	509376	F	Check over completely, repair as needed, and test at no charge
12858	700	29708	270 WIN	5-Aug-92	N	s	29-Dec-15	29-Dec-15	Delayed Firing - Firearms	Could Not Duplicate Concern	507939	F	Per Ilion - Replace TA & test @ n/c
12856	700	84218	308 WIN	31-Jan-12	N	s	29-Dec-15	29-Dec-15	Fired on Safe Release	Altered Adjustments or Components	507901	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12857	SEVEN	24743	308 WIN	1-Aug-02	N	s	29-Dec-15	18-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	507906	F	Per Ilion - Replace TA & test @ n/c
12859	597	26536	17 HMR	26-Sep-02	N	PD/S	29-Dec-15	29-Dec-15	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	507940	F	Per Ilion, converting to 22 WMR as requested by customer
12854	788	not avail.	6MM REM	4-Sep-73	Υ	s	29-Dec-15	29-Dec-15	Fired on Bolt Closing	Could Not Duplicate Concern	507870	F	Per Ilion - Check over, clean, test @ n/c - goodwill
12864	700	not avail.	3006 SPRG	13-Sep-76	N	5	31-Dec-15	31-Dec-15	Fired on Safe Release	Could Not Duplicate Concern	508013	F	Per Ilion - Replace TA & test @ n/c
12863	700	25815	7MM REM MA	7-Sep-04	N	s		31-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508001	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12868	700	25803	7MM REM MA	7-Oct-86	N	S	31-Dec-15	31-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508030	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12869	700	N/A	7MM REM MA	29-Oct-71	N	s	31-Dec-15	31-Dec-15	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508029	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12867	715	85800	243 WIN	16-Nov-06	Y	s	31-Dec-15	5-Feb-16	Fired on Safe Release	Altered Adjustments or Components	508021	F	Per Ilion - Repair at n/c - goodwill
12874	DPMS A-15	60531	223 REM	14-Jul-15	N	PD/S	4-Jan-16	20-Jan-16	Fired Out of Battery	Other - Unspecified or Undetermined - Firearms	508817	F	Returned as Received
12885	870	81283	20 GA	17-Jul-14	N	PD/S	5-Jan-16	21-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508815	F	Check over completely, repair as needed, and test at no charge
12883	700	not avail.	270 WIN	11-May-80	N	PD/S	6-Jan-16	22-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508180	F	Per Ilion - Replace TA & test @ n/c
12880	700	not avail.	3006 SPRG	27-Aug-76	N	PD/S	6-Jan-16	28-Jan-16	Fired on Safe Release	Could Not Duplicate Concern	508182	F	Per Ilion - Replace TA & test @ n/c
12882	770	85646	270 WIN	24-Aug-11	Y	PD/S	6-Jan-16	6-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508098	F	Per Ilion - Replace TA & test @ n/c
12884	700	not avail.	270 WIN	1-Apr-68	N	s	6-Jan-16	25-Jan-16	Fired on Bolt Closing	Improper Maintenance	508181	F	Per Ilion - Replace TA & test @ n/c
12879	700	85336	3006 SPRG	3-Apr-14	N	5	6-Jan-16	6-Jan-16	Fired on Safe Release	Altered Adjustments or Components	508141	F	Per Ilion - Replace TA & test @ n/c
12878	770	85648	300 WIN	27-May-09	Y	s	6-Jan-16	6-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508139	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12886	887	82540	12 GA	17-Oct-13	N	s	6-Jan-16	6-Jan-16	Failed to Extract	Could Not Duplicate Concern	508120	F	Replace with Ramac 81198 in exchange
12899	700	not avail.	22-250 REM	23-Feb-79	N	s	8-Jan-16	27-Jan-16	Fired on Bolt Closing	Could Not Duplicate Concern	508262	F	Per Ilion - Replace TA & test @ n/c

					-								Per Ilion - Replace TA & test
12896	700	not avail.	243 WIN	21-Nov-75	N	S	8-Jan-16	8-Jan-16	Fired on Bolt Closing	Improper Maintenance	508236	F	@ n/c
									-	Could Not Duplicate			Per Ilion - Replace TA & tes
12897	700	27253	270 WSM	2-May-06	N	S	8-Jan-16	8-Jan-16	Fired on Safe Release	Concern	508272	F	@ n/c
													Per Ilion - Replace TA & tes
12902	700	27478	3006 SPRG	24-May-02	N	S	8-Jan-16	8-Jan-16	Fired on Safe Release	Improper Maintenance	508312	F	@ n/c
													Per Ilion- Check over
			W (040 100 100 100 1	. W CO. S. C. S									completely and repair as
12895	783	85782	243 WIN	28-Aug-15	N	S	8-Jan-16	8-Jan-16	Fired With Safe ON	Broken or Missing Parts	508261	F	needed at no charge
	0.000				100	12		227.02		Altered Adjustments or		-	
12898	710	27410	3006 SPRG	10-May-04	Υ	S	8-Jan-16	9-Feb-16	Fired on Bolt Closing	Components	508263	- 1	Replace w/85846 in exchang
12929	783	85847	308 WIN	10-Mar-15	N	s	11-Jan-16	29-Jan-16	Fired on Safe Release	Other - Unexamined	n/a	F	Refunded purchase price.
12525	703	0304/	300 14114	10-14/81-13	14		11-1011-10	23-7811-10	Fired on Sale Release	Other - Onexammed	nya	- 1	Per Ilion - Replace TA & test
12928	700	29709	270 WIN	7-Apr-93	N	s	13-Jan-16	13-Jan-16	Fired on Bolt Closing	Improper Maintenance	508509	F	@ n/c
		45.45	0.0 0,00					20,701,20	This of the country	anproper trialities and		- 1	Per Ilion - Replace TA & test
12921	700	not avail.	3006 SPRG	1-Sep-74	N	s	13-Jan-16	13-Jan-16	Fired on Safe Release	Improper Maintenance	508410	F	@ n/c
						-				Altered Adjustments or			Per Ilion - Replace TA & test
12922	700	not avail.	6MM REM	12-Jul-73	N	S	13-Jan-16	27-Jan-16	Fired on Bolt Closing	Components	508338	F	@ n/c
			-11111111111111111111111111111111111111										
													Per Ilion, check over
			5000000000							Could Not Duplicate			completely, repair as needed
12926	783	85847	308 WIN	12-Mar-15	N.	S	13-Jan-16	13-Jan-16	Fired on Safe Release	Concern	508343	F	and test at no charge.
	200000000000000000000000000000000000000				100071	10				Could Not Duplicate			Per Ilion - Replace TA & test
12925	SEVEN	85419	300 BLK OU	28-Aug-12	N	S	13-Jan-16	13-Jan-16	Fired on Safe Release	Concern	508390	F	@ n/c
													42-42-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-
													Per Ilion, check over
12914	870	81125	12 GA	11.00		PD/S	12 1 16	0.5-1-15	First Cut of Favors	Clause Paul	500440		completely, repair as needed
12914	8/0	81125	12 GA	14-Jan-15	N	PD/S	13-Jan-16	9-Feb-16	Fired Out of Battery	Slow to Peak Could Not Duplicate	508440	F	and test at no charge.
12917	870	25583	20 GA	11-Sep-13	N	s	13-Jan-16	9-Feb-16	Fired With Safe ON	Concern	508406	F	Per Ilion - Repair at n/c
1231/	6/0	23363	20 GA	11-3ch-13	14	,	13-7611-10	3-1-60-10	Fired With Sale ON	Could Not Duplicate	308400	-	Per Ilion - Check over, clean,
12927	552	25594	22 RF	19-May-15	N	s	13-Jan-16	13-Jan-16	Fired on Safe Release	Concern	508463	F	test @ n/c
				33 11107 30		-	20.70.7 20	20.70.740	The constant in the constant	Altered Adjustments or		1	Replace TA & test @ n/c -
12948	700	27092	243 WIN	21-Nov-06	N	PD/S	15-Jan-16	18-Jan-16	Fired on Bolt Closing	Components	508656	F	goodwill
		1						700700000	Fired on Bolt	Could Not Duplicate			Per Ilion - Replace TA & test
12939	700	not avail.	270 WIN	13-Oct-71	N	5	15-Jan-16	29-Jan-16	Opening	Concern	508633	F	@ n/c
									Unexplained				
			W0000000000						Discharge - No	WEST PROBLEM STORY			
			300 WIN						Mention of Safety	Could Not Duplicate			Per Ilion - Replace TA & test
12945	700	not avail.	MA	1-Sep-66	N	S	15-Jan-16	28-Jan-16	Position	Concern	508635	F	@ n/c
		5.00	1300000000		3355	1 50	1000 July 1		22 W. SEVERS	Could Not Duplicate			Per Ilion - Replace TA & test
12940	700	not avail.	3006 SPRG	25-Feb-77	N	S	15-Jan-16	28-Jan-16		Concern	508598	F	@ n/c
									Unexplained				
									Discharge - No				
17040	700	man morall	2005 5005	7571		- 2	15 100 15	70 Inn 15	Mention of Safety	Could Not Duplicate	FORFOR	F	Per Ilion - Replace TA & test
12949	700	not avail.	3006 SPRG	7-Sep-71	N	5	15-Jan-16	28-Jan-16	Position Unexplained	Concern	508596	- 1	@ n/c
									Discharge - No				
									Mention of Safety	Could Not Duplicate			Per Ilion - Replace TA & test
12946	700	not avail.	6MM REM	13-May-71	N	s	15-Jan-16	15-Jan-16	Position	Concern	508597	F	@ n/c
22,540	700	HOL GYAIL.	S.THYLINGIVI	25 may /1			23-7411-10	23-7011-10	r valuon	Could Not Duplicate	300337	- 1	Per Ilion - Replace TA & test
12943	SEVEN	24784	6MM REM	12-May-83	N	5	15-Jan-16	15-Jan-16	Fired on Bolt Closing	Concern	508663	F	@ n/c
		2.7.2.7				-			, , , , , , , , , , , , , , , , , , ,	Could Not Duplicate		1	Per Ilion - Check over, clean,
12947	788	not avail.	243 WIN	7-Jun-77	Y	s	15-Jan-16	9-Feb-16	Fired on Bolt Closing	Concern	508586	F	test @ n/c
		11/2-2-2-2-2	1000		-	-		C 11 11 11 11 11 11 11 11 11 11 11 11 11	Unexplained		7.77.77	1	535575465
									Discharge - No				
			7MM REM						Mention of Safety	Could Not Duplicate			Per Ilion - Replace TA & test
12952	700	25803	MA	18-Oct-87	N	S	18-Jan-16	28-Jan-16	Position	Concern	508634	F	@ n/c
			22-250							Altered Adjustments or			Per Ilion - Replace TA & test
12962	700	not avail.	REM	5-Dec-77	N	S	20-Jan-16	29-Jan-16	Fired on Safe Release	Components	508748	F	@ n/c

12964	700	25797	280 REM	28-Feb-01	N	s	20-Jan-16	28-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508804	F	Per Ilion - Replace TA & test @ n/c
			7MM-08			-			Other - Firearms -	Could Not Duplicate			Per Ilion - Replace TA & test
12959	700	26285 85781	REM 308 WIN	20-May-10 27-Aug-15		5	20-Jan-16 20-Jan-16	20-Jan-16	XMP Update Fired on Bolt Closing	Concern Broken or Missing Parts	508802	F	Check over completely, repair as needed, and test at no
12960	700	not avail.	3006 SPRG	26-Jun-78	N	s	20-Jan-16	9-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508803	F	Per Ilion - Replace TA & test @ n/c
12954	710	27410	3006 SPRG	22-Jun-06	Υ	S	20-Jan-16	5-Feb-16	Fired With Safe ON	Altered Adjustments or Components	508844	F	
12957	700	25773	3006 SPRG	40.500		s	201-15	20-Jan-16	F	Could Not Duplicate	508749	F	Per Ilion - Replace TA & test
				10-Sep-90	N		20-Jan-16		Fired on Bolt Closing	Concern Could Not Duplicate			@ n/c
12958	788	not avail.	243 WIN	1-Jun-68	Y	5	20-Jan-16	20-Jan-16	Fired on Bolt Closing	Concern Could Not Duplicate	508751	F	Per Ilion - Check over & clean Per Ilion - Replace TA & test
12970	700	27267	270 WIN	8-Feb-07	N	s	25-Jan-16	10-Feb-16	Fired on Safe Release	Concern	508912	F	
12973	700	25793	3006 SPRG	23-Jan-03	N	s	25-Jan-16	11-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	508910	F	Per Ilion - Replace TA & test @ n/c
12972	710	27414	300 WIN	14-Jul-05	Y	5	25-Jan-16	23-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509005	F	Per Ilion - Replace TA & test
12372	710	2/414	1405	14-701-03	3.1	3	23-3411-10	23-760-10	Position	Could Not Duplicate	303003	-	e iye
12981	887	82500	12 GA	5-Mar-10	Y	S	25-Jan-16	10-Feb-16	Fired on Bolt Closing	Concern	509012	F	Per Ilion - Repair at n/c
12979	700	26189	22-250 REM	20-Dec-04	N	5	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509002	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12980	700	25606	25-06 REM	13-Nov-91	N	s	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509003	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12971	700	N/A	3006 SPRG	15-Sep-75	N	5	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	508867	F	Per Ilion, check over completely, repair as needed,
12978	700	27480	7MM REM MA	27-Mar-00	N	S	25-Jan-16	25-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509004	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12976	770	85631	7MM-08 REM	30-Jul-12	N	5	25-Jan-16	25-Jan-16	Fired on Bolt Opening	Could Not Duplicate Concern	508909	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12974	887	82540	12 GA	31-Jul-13	N	5	25-Jan-16	25-Jan-16	Fired Out of Battery	Could Not Duplicate Concern	508866	F	Consumer Service is replacing gun
17000	700		2201405	37.0-1.72		00.45	22 1	22 5-1	F - 1 C-1 - D-1	Could Not Duplicate	500110	_	Per Ilion - Replace TA & test
12988	700	not avail. 85632	270 WIN	27-Oct-70	N	PD/S	27-Jan-16	23-Feb-16	Fired on Safe Release	Concern Could Not Duplicate	509110	F	@ n/c
12987	770	not avail.	270 WIN 3006 SPRG	9-Aug-12 20-Mar-73	Y N	PD/S	27-Jan-16	25-Feb-16 29-Feb-16		Concern Altered Adjustments or Components	509077	F	Per Ilion - Replace TA & test
12985	700	25813		20-War-73	N	5	27-Jan-16		Fired on Bolt Closing	AFT MKT TRIGGER ASSM	509109	F	Per Ilion - Replace TA & test

12984	700	26323	7MM SAUM	19-May-03	N	s	27-Jan-16	1-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509055	F	Per Ilion - Replace TA & test
12994	700	N/A	243 WIN	14-Nov-75	N	s	27-Jan-16	27-Jan-16	Fired With Safe ON	Could Not Duplicate Concern	509072	F	
12996	700	N/A	25-06 REM	9-Feb-71	N	s	27-Jan-16	27-Jan-16	Fired on Safe Release	Altered Adjustments or Components	509071	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12991	700	not avail.	3006 SPRG	4-Mar-82	N	s	27-Jan-16	27-Jan-16	Safety not working properly	Could Not Duplicate Concern	509073	F	Per Ilion - Replace TA & test
12997	700	N/A	6MM REM	5-Apr-74	N	s	27-Jan-16	27-Jan-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	509130	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
12992	700	27480	7MM REM MA	1-May-02	N	5	27-Jan-16	27-Jan-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509131	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
										Altered Adjustments or			Per Ilion, replace trigger assembly, check over, and
12993	SEVEN	N/A	308 WIN	31-Aug-88	N	S	27-Jan-16	27-Jan-16	Fired on Bolt Closing	Components	509132	F	test fire at no charge
13005	597	26581	22 WMR	4-Sep-01	N	s	29-Jan-16	3-Feb-16	Fired Out of Battery	Could Not Duplicate Concern	509186	F	Per Ilion, check over completely, repair as needed and test at a 50% discount.
13003	700	not avail.	243 WIN	1-Sep-74	N	S	29-Jan-16	23-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	509247	F	Per Ilion - Replace TA & test
									Fired on Bolt	Could Not Duplicate		Ť	Per Ilion - Replace TA & test
13004	700	not avail.	243 WIN	25-Apr-78	N	S	29-Jan-16	9-Feb-16	Opening	Concern	509204	F	@ n/c
13007	700	not avail.	300 WIN MA	31-Jan-73	N	s	29-Jan-16	8-Feb-16	Fired on Bolt Closing	Altered Adjustments or Components Could Not Duplicate	509205	F	Per Ilion - Replace TA & test @ n/c Per Ilion - Replace TA & test
13006	700	not avail.	3006 SPRG	13-Mar-69	N	5	29-Jan-16	9-Feb-16	Fired on Safe Release	Concern	509248	F	@ n/c
13000	887	82540	12 GA	7-May-12	Y	s	29-Jan-16	23-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509250	F	Per Ilion - Repair at n/c
13002	H&R Handi- Rifle	72430	300 BLACKO	12-Apr-13	N	s	29-Jan-16	29-Jan-16	Delayed Firing - Firearms	Could Not Duplicate Concern	509174	F	Per Ilion, check over completely, repair as needed and test at no charge
13017	700	not avail.	6MM REM	27-Oct-77	N	5	2-Feb-16	24-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509311	F	
13014	700	not avail.	7MM REM MA	30-Aug-78	N	s	2-Feb-16	25-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509308	F	Per Ilion - Replace TA & test @ n/c
13018	700	not avail.	8MM REM MA	25-Jun-77	N	s	2-Feb-16	24-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509324	F	Per Ilion - Replace TA & test @ n/c Check over completely, repair
13021	1187	29674	12 GA	11-Dec-95	N	s	2-Feb-16	2-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	509313	F	as needed, and test at no charge
12012	700 141	33500	FOCAL	9 tul 00			3 Feb 25	25 Feb 15	Fixed on Safe Release	Could Not Duplicate	F00300		Per Ilion - Replace TA & test
13013	700 ML	27588	50 CAL	8-Jul-98	N	5	2-Feb-16	25-Feb-16	Fired on Safe Release Unexplained Discharge - No	Concern	509309	F	@ n/c
13015	700	not avail.	243 WIN	17-Nov-00	N	5	2-Feb-16	2-Mar-16	Mention of Safety Position	Could Not Duplicate Concern	509307	F	
13177	700	not avail.	270 WIN	Z-Apr-81	N	S	2-Feb-16	9-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509306	F	Per Ilion - Replace TA & test @ n/c

13029	700	85433	223 REM	14-Feb-12	N	s	4-Feb-16	24-Feb-16	Fired on Safe Release	Could Not Duplicate Concern	509408	F	Per Ilion - Replace TA & test @ n/c
13026	700	not avail.	25-06 REM	5-Jan-72	N	s	4-Feb-16	25-Feb-16	Fired on Bolt Opening	Could Not Duplicate Concern	509410	F	Per Ilion - Replace TA & test
	700		3006 SPRG	27-Nov-68	N	S	4-Feb-16	25-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509409	F	Per Ilion - Replace TA & test
13027	50.00 s	not avail.	7MM REM	Terrorren secon			2.500.000	100000000		Could Not Duplicate	te control		Per Ilion - Replace TA & test
13033	700	not avail.	MA	26-Apr-79	N	5	4-Feb-16	9-Feb-16	Fired on Bolt Closing	Concern Altered Adjustments or	509430	F	@ n/c Per Ilion - Replace TA & tes
13032	721	not avail.	3006 SPRG	1-Feb-53	Y	S	4-Feb-16	9-Feb-16	Fired on Safe Release	Components	509429	F	@ n/c
13028	770	85652	270 WIN	15-Oct-13	γ	s	4-Feb-16	4-Feb-16	Fired on Bolt Opening	Could Not Duplicate Concern	509377	F	Per Ilion - Replace TA & test @ n/c
13030	700	26080	7MM WEATHE	21-Jul-92	N	s	4-Feb-16	1-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509407	F	Per Ilion - Replace TA & test @ n/c
13034	783	85837	308 WIN	13-Sep-13	N	S	4-Feb-16		Fired on Bolt Closing	Other - Unexamined		F	
	-0.05000	200000	7MM-08	12302-1210-20	83.0		200000000		and carried	Altered Adjustments or	220000000		57-37 - 92-7-2-10-33 - 10
13045	SEVEN	24741	REM	20-Feb-96	N	PD/S	8-Feb-16	26-Feb-16	Comment of the Commen	Components	509520	F	Replace TA & test @ n/c
13037	700	not avail.	270 WIN	8-Jan-85	N	s	8-Feb-16	29-Feb-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	509572	F	Per Ilion - Replace TA & test @ n/c
	700	20100	2005 5005							Could Not Duplicate		Ι.	Per Ilion - Replace TA & test
13046	700	27478	3006 SPRG	27-Oct-95	N	S	8-Feb-16	26-Feb-16	Fired on Safe Release Unexplained	Concern	509517	F	@ n/c
13049	700	not avail.	3006 SPRG	24-Jul-78	N	s	8-Feb-16	25-Feb-16	Discharge - No Mention of Safety Position	Altered Adjustments or Components	509570	F	Per Ilion - Replace TA & test @ n/c
										Could Not Duplicate		١.	Per Ilion - Replace TA & test
13052	700	not avail.	3006 SPRG	8-Jun-73	N	S	8-Feb-16	25-Feb-16	Fired With Safe ON Unexplained Discharge - No Mention of Safety	Concern Could Not Duplicate	509552	F	@ n/c Per Ilion - Replace TA & test
13038	700	25775	308 WIN	3-Aug-90	N	S	8-Feb-16	29-Feb-16	Position	Concern	509573	F	@ n/c
13043	700		7MM REM			s	8-Feb-16	26-Feb-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate		F	Per Ilion - Replace TA & test
13043	700	not avail.	IVIA	20-Mar-72	N	2	8-Feb-16	26-Feb-16	Position	Concern Altered Adjustments or	509521	-	@ n/c Per Ilion - Replace TA & test
13048	770	85632	270 WIN	10-Dec-08	Υ	S	8-Feb-16	29-Feb-16	Fired on Safe Release	Components	509571	F	@ n/c
13047	700	not avail.	243 WIN	20-Oct-77	N	s	8-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509566	F	Per Ilion - Replace TA & test @ n/c
13040	700	25789	25-06 REM	24-Jan-86	N	S	8-Feb-16	7-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	509524	F	Per Ilion - Replace TA & test
13044	700	not avail.	25-06 REM	6-Jun-78	N	s	8-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	509523	F	Per Ilion - Replace TA & test
13036	700	25773	3006 SPRG	25-Nov-85	N	s	8-Feb-16		Fired on Safe Release	Altered Adjustments or Components	509574	F	Per Ilion - Replace TA & test @ n/c
13042	700	25773	3006 SPRG	0-05.44000000000000	N	s	8-Feb-16	4-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509522	F	Per Ilion - Replace TA & test

	01.501	AND DOOR OF THE PERSON OF THE	1777247007	**************************************	·	777		THE PERSON NAMED IN	I CONTRACTOR OF THE SOCIETY.	Could Not Duplicate	0.0000000000000000000000000000000000000		Call Center issued a refund to
13039	887	82500	12 GA	20-Dec-13	Y	S	8-Feb-16	7-Mar-16	Fired With Safe ON	Concern	509493	F	
13051	1187	25337	12 GA	27-Sep-00	N	s	8-Feb-16	7-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509553	F	Per Ilion - Repair at n/c - goodwill
13053	1100	N/A	12 GA	11-Nov-71	N	s	10-Feb-16	10-Feb-16	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms	509665	F	Per Ilion quote to check ove completely, repair, and test at a 50% discount
13059	700	not avail.	3006 SPRG	12-Jun-79	N	s	10-Feb-16	1-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509666	F	Per Ilion - Replace TA & test @ n/c
13055	700	27343	7MM REM MA	23-May-05	N	5	10-Feb-16	8-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509662	F	Per Ilion - Replace TA & test
13057	700	27125	7MM REM MA	1-Feb-06	N	s	10-Feb-16	8-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	509663	F	Per Ilion - Replace TA & test @ n/c
13060	700	not avail.	7MM REM MA	19-Oct-70	N	5	10-Feb-16	8-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509664	F	Per Ilion - Replace TA & test @ n/c
13056	40-X	27225	308 WIN	10-Apr-07	N	5	10-Feb-16	1-Mar-16	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	509667	F	Per Ilion - Replace TA & test @ n/c
13066	582	29856	22 RF	17-May-79	Υ	s	11-Feb-16	11-Feb-16	Fired on Safe Release	Improper Maintenance	509724	F	Per Ilion - Check over, clean, test @ n/c
13096	597	26536	17 HMR	20-Nov-02	N	PD/S	11-Feb-16	7-Mar-16	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	510265	F	Consumer Service is refunding purchase price
13064	700	26033	270 WIN	12-Oct-01	N	S	11-Feb-16	2-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	509703	F	Per Ilion - Replace TA & test @ n/c
13065	700	not avail.	3006 SPRG	13-Mar-75	N	S	11-Feb-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509705	F	Per Ilion - Replace TA & test
13067	700	not avail.	3006 SPRG	4-Apr-75	N	s	11-Feb-16	2-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	509701	F	Per Ilion - Replace TA & test @ n/c
13068	700	85375	7MM REM MA	10-Nov-11	N	s	11-Feb-16	2-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509706	F	Per Ilion - Replace TA & test @ n/c
13082	870	25583	20 GA	22-Oct-93	N	s	15-Feb-16	15-Feb-16	Fired With Safe ON	Could Not Duplicate Concern	509842	F	Per Ilion, check over completely, repair, and test at no charge
13075	PARDNER PUMP	72262 not avail.	20 GA 270 WIN	23-Jul-15 1-Apr-67	N N	s	15-Feb-16	15-Feb-16 2-Mar-16	Fired With Safe ON	Other - Unspecified or Undetermined - Firearms Altered Adjustments or Components	509820 509838	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge Per Ilion - Replace TA & test @ n/c
13074	700	not avail.	3006 SPRG	2-Jul-74	N	5		2-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509795	F	Per Ilion - Replace TA & test
13077	700	not avail.	3006 SPRG	21-Oct-81	N	5		15-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509792	F	Per Ilion - Replace TA & test
13083	700	not avail.	308 WIN	1-Nov-67	N	5			Fired on Bolt Closing	Could Not Duplicate Concern	509843	F	Per Ilion - Replace TA & test

13079	700	not avail.	7MM REM MA	23-Oct-79	N	S	15-Feb-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509794	F	Per Ilion - Replace TA & test @ n/c
13076	710	27404	270 WIN	28-Nov-01	Y	s	15-Feb-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	509793	F	Replace w/85844 in exchange
13080	770	85632	270 WIN	21-Oct-09	Y	s	15-Feb-16	5-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	509844	F	Replace w/85844 in exchange
13091	700	84019	MA MA	17-Dec-08	N	PD/S	17-Feb-16	9-Mar-16	Fired With Safe ON Fired on Bolt	Could Not Duplicate Concern Could Not Duplicate	509962	F	Replace TA & test @ n/c Per Ilion - Replace TA & test
13093	700	25787	243 WIN	20-Apr-95	N	S	17-Feb-16	10-Mar-16	Opening	Concern Could Not Duplicate	509907	F	@ n/c Per Ilion - Replace TA & test
13097	700	25771	270 WIN	21-Sep-87	N	S	17-Feb-16	8-Mar-16	Fired on Safe Release	Concern Could Not Duplicate	509949	F	@ n/c Per Ilion - Replace TA & test
13089	700	not avail.	3006 SPRG	29-May-74	N	s	17-Feb-16	24-Mar-16	Fired on Safe Release	Concern	509964	F	@ n/c
13095	700	25859	3006 SPRG	28-Oct-95	N	s	17 Feb 16	15-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	509950	F	Per Ilion - Replace TA & test
									Unexplained Discharge - No Mention of Safety	Altered Adjustments or			Per Ilion - Replace TA & test
13098	700	not avail.	3006 SPRG 7MM REM	28-Feb-79	N	S	17-Feb-16	4-Mar-16	Position Unexplained Discharge - No Mention of Safety	Components Could Not Duplicate	509905	F	@ n/c Per Ilion - Replace TA & test
13090	700	not avail.	MA	3-Mar-69	N	s	17-Feb-16	17-Mar-16	Position	Concern	509963	F	@ n/c
13094	710	27408	270 WIN	11-Nov-05	Υ	s	17-Feb-16	17-Mar-16	Unexplained Discharge - No Mention of Safety Position Fired on Bolt	Altered Adjustments or Components	509906	F	Per Ilion - Replace TA & test @ n/c
13092	700	20000 N/A	308 WIN	1-Aug-69	N	PD/S	17-Feb-16	19-Feb-16	Opening Unexplained Discharge - No Mention of Safety Position	Other - Unexamined Altered Adjustments or Components	510023	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
13105	700	25791	270 WIN	13-Dec-89	N	S	19-Feb-16	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510014	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
13101	700	26129	3006 SPRG	23-Apr-01	N	5	19-Feb-16	19-Feb-16		Could Not Duplicate Concern	509990	F	Per Ilion - Replace TA & test
13109	700	N/A	3006 SPRG	13-Sep-71	N	s		19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510013	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
13102	770	85632	270 WIN	16-Feb-12	Y	S	19-Feb-16	19-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510011	F	Per Ilion, replace trigger assembly, check over, and test fire at no charge
13103	710	27410	3006 SPRG	10-Aug-04	Y	s	19-Feb-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	510012	F	Replace w/85846 in exchange, Ck for \$54 (transfer fee)

13110	700	27095	3006 SPRG	27-Aug-10	N	PD/S	19-Feb-16	11-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510024	F	Per Release - Reimburse for truck repair & tire replacement (\$1,634.83)
13118	700	not avail.	3006 SPRG	22-Aug-84	N	s	23-Feb-16	23-Feb-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	510077	F	Per Ilion - Replace TA & test @ n/c
13115	870	25098	12 GA	6-Nov-09	N	S	23-Feb-16	23-Feb-16	Jamming/Feeding issues	Other - Unspecified or Undetermined - Firearms	510141	F	llion repaired at n/c - goodwill
13123	700	not avail.	270 WIN	5-May-77	N	PD/S	23-Feb-16	10-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510119	F	Per Ilion - Replace TA & test @ n/c
13117	700	not avail.	25-06 REM	19-Mar-81	N	S	23-Feb-16	16-Mar-16	Fired on Bolt Opening	Altered Adjustments or Components	510116	F	Per Ilion - Replace TA & test @ n/c
13121	700	26096	300 RUM	21-Feb-00	N	s	23-Feb-16	22-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510079	F	Per Ilion - Replace TA & test @ n/c
13119	700	25955	3006 SPRG	22-May-02	N	s	23-Feb-16	10-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510117	F	Per Ilion - Replace TA & test @ n/c
13122	700	not avail.	3006 SPRG	1-Sep-74	N	s	23-Feb-16	17-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510078	F	Per Ilion - Replace TA & test @ n/c
13120	700	not avail.	7MM REM MA	24-Oct-75	N	s		22-Mar-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate Concern	510118	F	Per Ilion - Replace TA & test @ n/c
	600	la service de	6MM REM		Υ	s		25-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	510271	F	Per Ilion - Replace TA & test
13130	700	not avail.	7MM REM	15-Aug-77	N	5	25-Feb-16	25-Feb-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510198	F	@ n/c Per Ilion - Replace TA & test @ n/c
13134	SEVEN	24741	7MM-08 REM	7-Oct-96	N	S	25-Feb-16	25-Feb-16	Fired on Bolt Closing	Could Not Duplicate Concern	510181	F	Per Ilion - Replace TA & test @ n/c
13137	700	not avail.	243 WIN	5-Apr-79	N	5	25-Feb-16	28-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510243	F	Per Ilion - Replace TA & test @ n/c
13131	700	not avail.	7MM REM MA	1-Nov-74	N	s	25-Feb-16	16-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	510246	F	Per Ilion - Replace TA & test @ n/c
13145	700	not avail.	270 WIN	30-Apr-76	N	5	1-Mar-16		Fired on Bolt Closing	Altered Adjustments or Components	510332	F	Per Ilion - Replace TA & test @ n/c
13141	700	not avail.	300 WIN MA	16-Aug-74	N	s	1-Mar-16	2-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	510298	F	Per Ilion - Replace TA & test @ n/c
13142	710	27408	270 WIN	3-Sep-04	Υ	5	1-Mar-16		Fired on Bolt Closing	Altered Adjustments or Components	510300		Replace w/85844 in exchange
13140	770	85637	243 WIN	20-Jan-09	Y	s	1-Mar-16	2-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510337	F	Per Ilion - Replace TA & test
13146	870	25100	12 GA	8-Feb-13	N	s	1-Mar-16	1-Mar-16	Fired Out of Battery	Could Not Duplicate Concern	510323	F	Per Ilion, check over completely, repair, and test at no charge
13150	700	84600	223 REM	9-Aug-11	N	PD/S	2-Mar-16	30-Mar-16		Could Not Duplicate Concern	510859	F	
13158	597	26514	17 HMR	27-Dec-04	N	PD/S	3-Mar-16	3-Mar-16	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	510400	F	Per Ilion, converting to 22 WMR as requested by consumer

13166	660	not avail.	308 WIN	1-Dec-68	Υ	s	3-Mar-16	8-Mar-16	Fired on Safe Release	Improper Maintenance	510468	F	
13159	700	29709	270 WIN	29-Sep-04	N	s	3-Mar-16	8-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510401	F	Per Ilion - Replace TA & tes @ n/c
13153	700	25807	300 WIN	22-Mar-90	N	S	3-Mar-16	3-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510424	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13156	700	25793	3006 SPRG	7-0ct-91	N	s	3-Mar-16	3-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510423	F	Per Ilion - Replace TA & test
13157	700	not avail.	3006 SPRG	1-Feb-68	N	s	3-Mar-16	8-Mar-16	Fired on Bolt Closing	Improper Maintenance	510404	F	Per Ilion - Replace TA & test @ n/c
13160	710	27410	3006 SPRG	18-Mar-03	Y	s	3-Mar-16	8-Mar-16	Fired on Bolt Closing	Improper Maintenance	510483	F	Replace in exchange with
13165	887	82578	12 GA	12-Feb-14	Y	5	3-Mar-16	3-Mar-16	Safety not working properly	Could Not Duplicate Concern	510411	F	Per Ilion, check over completely, repair, and test at no charge
13169	700	N/A	3006 SPRG	2-May-74	N	s	7-Mar-16	7-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510554	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13172	700	26287	3006 SPRG	20-Apr-01	N	5	7-Mar-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510553	F	Per Ilion - Replace TA & test
-		2100							Unexplained Discharge - No Mention of Safety	Other - Unspecified or	N STANDACT		Per Ilion, replace trigger, repair, check over completely, and test at no
13174	700	N/A	3006 SPRG	21-Mar-69	N	5	7-Mar-16	7-Mar-16	Position	Undetermined - Firearms	510552	F	charge
13173	788	not avail.	243 WIN	26-Jan-79	Y	s	7-Mar-16	9-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510595	F	Per Ilion - Check over, clean, test @ n/c - goodwill
13170	700 ML	27572	50 CAL	16-Sep-97	N	S	7-Mar-16	9-Mar-16	Unexplained Discharge - No Mention of Safety Position	Broken or Missing Parts	510551	F	Per Ilion - Replace TA & test
13171	78 Sportsman	not avail.	270 WIN	9-Apr-88	Y	PI/S	7-Mar-16	14-Apr-16	Fired on Safe Release	Other - Unspecified or Undetermined - Firearms	510610	F	Per Ilion - Replace TA & test @ n/c
13178	770	85637	243 WIN	4-Nov-11	γ	PI/S	8-Mar-16		Fired on Safe Release	Other - Unexamined		F	
13187	700	25714	223 REM	16-May-13	N	s	10-Mar-16	11-Mar-16	Fired on Bolt Closing	Other - Unspecified or Undetermined - Firearms	510653	F	Per Ilion - Replace TA & test @ n/c
13182	700	27092	243 WIN	11-May-10	N	s	10-Mar-16	11-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510758	F	Per Ilion - Replace TA & test @ n/c
13184	700	84170	243 WIN	13-Nov-06	N	5		10-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510710	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13191	700	not avail.	243 WIN	28-Apr-71	N	s	10-Mar-16	11-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510706	F	
13188	700	29712	3006 SPRG	25-Jun-92	N	s	10-Mar-16	10-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	510685	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13189	700	not avail.	3006 SPRG	28-Jul-76	N	S	10-Mar-16	11-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	510707	F	THE PROPERTY OF THE PROPERTY O
13186	700	N/A	308 WIN	12-Dec-80	N	S	10-Mar-16	10-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510709	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13183	700	25803	7MM REM MA	9-Nov-95	N	s	10-Mar-16	10-Mar-16	Fail to Fire	Could Not Duplicate Concern	510637	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13185	700	not avail.	270 WIN	29-Jan-73	N	PD/S	10-Mar-16	8-Apr-16	Fired on Safe Release	Altered Adjustments or Components	510708	F	Per Ilion - Replace TA & test @ n/c
13192	R-25	60032	308 WIN	12-Jul-11	N	PD/S	10-Mar-16	4-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	511170	F	Repair @ n/c - goodwill gesture
13193	700	85539	223 REM	28-Dec-12	N	s	31.Mar 16	22-Mar-16	Dissatisfied with	Could Not Duplicate	511159	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
15195	700	03339	7MM REM	28-060-12	IV.	3	11-10/01-10	ZZ-IVId1-16	Service - Fireditis	Could Not Duplicate	511155	+	charge
13194	700	N/A	MA	1-0ct-68	N	5	14-Mar-16	14-Mar-16	Fired on Safe Release	Concern	510875	F	
13196	700	N/A	7MM REM MA	5-Mar-70	N	s	14-Mar-16	14-Mar-16	Fired on Safe Release	Could Not Duplicate Concern	510862	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13197	710	27410	3006 SPRG	11-Apr-02	Y	S	14-Mar-16	14-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	510861	F	Replace in exchange with Ramac 85846 at no charge
				2000 000 000 000					Unexplained Discharge - No Mention of Safety	Altered Adjustments or	22222		Replace in exchange with
13198	710	27410	3006 SPRG	30-May-03	Υ	S	14-Mar-16	14-Mar-16	Position Unexplained Discharge - No	Components	510863	F	Per Ilion, replace trigger, repair, check over
13204	700	N/A	270 WIN	26-Apr-76	N	S	16-Mar-16	16-Mar-16	Mention of Safety Position	Could Not Duplicate Concern	510897	F	completely, and test at no charge
13206	770	85681	243 WIN	30-Sep-09	Y	s	16-Mar-16	16-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510949	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13205	770	85636	300 WIN	4-Oct-07	Υ	5	16-Mar-16	23-Mar-16	Fired on Bolt Closing	Altered Adjustments or Components	510940	F	CSR in the Call Center replaced rifle through SNC
13207	770	85632	270 WIN	31-May-13	Y	s		13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	510948	F	Per Ilion - Replace TA & test @ n/c
		1						-		Could Not Duplicate		Ť	Per Ilion - Replace TA & test
13212	700	not avail.	308 WIN 7MM REM MA	22-Apr-75	N	5		22-Mar-16	Fired on Safe Release Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	510989 511034	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13211	700	25793	3006 SPRG	18-Sep-13	N	S	18-Mar-16	18-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511032	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13218	700	N/A	7MM REM MA	1-Oct-64	N	s	22-Mar-16	22-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511152	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13217	700	25855	7MM-08 REM	18-Mar-03	N	s	22-Mar-16	23-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511153	F	Per Ilion - Replace TA & test @ n/c
13216	VERSA MAX	81045	12 GA	5-Mar-14	N	s	22-Mar-16	22-Mar-16	Blowback in Face	Could Not Duplicate Concern	511157	F	Per Ilion, check over completely, repair, and test at no charge
13221	700	N/A	270 WIN	25-Jan-79	N	s	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511263	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13224	700	N/A	270 WIN	12-Sep-77	N	s	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511262	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13225	700	N/A	3006 SPRG	31-Mar-75	N	5	24-Mar-16	24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	511272	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13229	700	N/A	7MM EXP	5-Oct-79	N	5		24-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511259	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
									Unexplained Discharge - No Mention of Safety	Altered Adjustments or	AATE SIANO S		Per Ilion, replace in exchange with Ramac 85844 at no
13230	710	27408	270 WIN	11-Mar-03	Y	S	24-Mar-16	24-Mar-16	Position Unexplained Discharge - No	Components	511258	F	charge Per Ilion, replace trigger, repair, check over
13226	710	27412	7MM REM MA	15-Feb-06	Υ	s	24-Mar-16	24-Mar-16	Mention of Safety Position	Altered Adjustments or Components	511257	F	completely, and test at no charge
									Unexplained Discharge - No Mention of Safety	Could Not Duplicate			Per Ilion, replace trigger, repair, check over completely, and test at no
13223	SEVEN	24787	223 REM	5-Mar-02	N	S	24-Mar-16	24-Mar-16	Position Unexplained Discharge - No	Concern	511261	F	charge Per Ilion, replace trigger, repair, check over
13228	SEVEN	24787	223 REM	5-Mar-02	N	s	24-Mar-16	24-Mar-16	Mention of Safety Position	Could Not Duplicate Concern Could Not Duplicate	511260	F	completely, and test at no charge Per Ilion - Replace TA & test
13231	700	25739	308 WIN	14-Nov-14	N	5	24-Mar-16	18-Apr-16	Fired on Safe Release Unexplained	Concern	511913	F	@ n/c Per Ilion, replace trigger,
13238	700	N/A	270 WIN	22-Aug-74	N	s	31-Mar-16	31-Mar-16	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511496	F	repair, check over completely, and test at no charge
13239	700	25771	270 WIN	16-Mar-84	N	s	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511497	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13237	700	N/A	3006 SPRG	27-Oct-72	N	5	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511495	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13243	700	27478	3006 SPRG	6-Jul-00	N	5		31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	511499	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13245	700	N/A	3006 SPRG	31-Aug-71	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511500	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13240	700	N/A	7MM REM MA	2-Jun-75	N	S	31-Mar-16	31-Mar-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511498	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13247	RM380	96454	380 ACP	15-Oct-15	N	S	31-Mar-16	31-Mar-16	Fired on Bolt Closing	Could Not Duplicate Concern	511378	F	Per Ilion, check over completely, repair, and test at no charge
13255	700	not avail.	243 WIN	5-Dec-78	N	s	4-Apr-16	14-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511610	F	Per Ilion - Replace TA & test @ n/c
13252	700	25851	270 WIN	16-Jun-98	N	s	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511606	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13254	700	27476	270 WIN	29-Oct-99	N	S	4-Apr-16	20-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	511605	F	Per Ilion - Replace TA & test @ n/c
13258	700	25630	270 WIN	5-Dec-88	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511607	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13259	700	26092	280 REM	29-Sep-92	N	s	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511604	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13257	700	N/A	3006 SPRG	1-Aug-68	N	s	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511608	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13253	700	26420	7MM REM MA	21-Aug-03	N	5	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511611	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13256	700	25855	7MM-08	6-May-98	N	5	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511612	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13260	SEVEN	24782	243 WIN	9-Apr-84	N	S	4-Apr-16	4-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511609	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13266	700	not avail.	243 WIN	15-May-72	N	PI/S	7-Apr-16	14-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511793	F	Per Ilion - Replace TA & test @ n/c
13264	700	not avail.	243 WIN	11-Jan-79	N	s	7-Apr-16	13-Apr-16	Fired on Bolt Closing	Improper Maintenance	511795	F	Per Ilion - Replace TA & test @ n/c
13265	700	not avail.	3006 SPRG	22-Oct-73	N	s	7-Apr-16	14-Apr-16		Could Not Duplicate Concern	511792	F	Per Ilion - Replace TA & test @ n/c
13273	700	N/A	243 WIN	9-Sep-88	N	s	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511791	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13274	700	N/A	270 WIN	28-Sep-82	N	5	8-Apr-16	8-Apr-16	Fired on Bolt Closing	Altered Adjustments or Components	511720	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13269	700	not avail.	3006 SPRG	4-Aug-71	N	5	8-Apr-16		Fired on Safe Release	Could Not Duplicate Concern	511789	F	Per Ilion - Replace TA & test

13275	700	N/A	3006 SPRG	8-May-72	N	S	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511705	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13270	700	not avail.	6MM REM	14-Apr-69	N	s	8-Apr-16	13-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511790	F	Per Ilion - Replace TA & test @ n/c
13272	700	N/A	7MM REM MA	1-Dec-66	N	s	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	511794	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13268	710	27410	3006 SPRG	19-Oct-05	Y	s	8-Apr-16	8-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511788	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13271	870	25587	12 GA	13-Feb-02	N	s	8-Apr-16	8-Apr-16	Delayed Firing - Firearms	Other - Unspecified or Undetermined - Firearms	511634	F	Per Ilion, check over completely, repair, and test at no charge
	CEVEN	24741	7MM-08	9.1400.05				pt_avertions	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	E11706		Per Ilion - Replace TA & test
13278	SEVEN		REM	8-Mar-96	N	S	8-Apr-16	20-Apr-16	Position	Could Not Duplicate	511706	F	@ n/c Per Ilion, replace trigger, repair, check over completely, and test at no
13292	600	N/A	308 WIN	1-Jan-67	Υ	S	12-Apr-16	12-Apr-16	Fired on Bolt Closing Unexplained	Concern	511910	F	charge Per Ilion, replace trigger,
			22-250						Discharge - No Mention of Safety				repair, check over completely, and test at no
13282	700	N/A	REM	8-Apr-69	N	S	12-Apr-16	12-Apr-16	Position Unexplained Discharge - No Mention of Safety	Improper Maintenance Could Not Duplicate	511956	F	Per Ilion, replace trigger, repair, check over completely, and test at no
13284	700	25791	270 WIN	30-Oct-95	N	s	12-Apr-16	12-Apr-16	Position	Concern	511954	F	charge
13289	700	N/A	3006 SPRG	23-Jul-81	N	5	12-Apr-16	12-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	511957	F	Per llion, replace trigger, repair, check over completely, and test at no charge
13283	700	N/A	6MM REM	7-Jun-71	N	5		12-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	511959	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13287	700	86483	7.62MM	26-Jun-15	N	5			Fired on Safe Release	Altered Adjustments or Components	511945	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13296	700	27011	270 WIN	3-Nov-14	N	s		13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate	511960	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13295	700	25793	3006 SPRG	14-Mar-85	N	s		13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	511955	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13297	700	25709	308 WIN	5-Jan-96	N	5		13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511962	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13298	700	N/A	7MM REM MA	23-Aug-78	N	s	13-Apr-16	13-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	511961	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13294	770	85637	243 WIN	5-Dec-12	Y	S	13-Apr-16	13-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	511958	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13309	700	85434	22-250 REM	28-Jun-12	N	S	15-Apr-16	20-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512060	F	Per Ilion - Replace TA & test @ n/c
13304	700	not avail.	243 WIN	6-Jun-77	N	s	15-Apr-16	21-Apr-16	Fired on Safe Release	Altered Adjustments or Components	512048	F	Per Ilion - Replace TA & test @ n/c
13301	700	not avail.	3006 SPRG	17-Jun-79	N	s		21-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512051	F	Per Ilion - Replace TA & test
13311	700	N/A	3006 SPRG	14-Jan-88	N	s	15-Apr-16	15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	512053	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13310	700	85435	308 WIN	17-Jun-09	N	5	15-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512046	F	Of Principle
13302	710	27416	243 WIN	8-Oct-06	Y	S	15-Apr-16	15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	512026	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13308	710	27410	3006 SPRG	15-Feb-01	Y	s		27-Apr-16		Could Not Duplicate Concern	512050		Replace w/85846 in exchange
13303	770	85655	270 WIN	3-May-13	Y	5		15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512049	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13299	887	82500	12 GA	18-Feb-14	Y	s	15-Apr-16	19-Apr-16	Fired on Bolt Closing	Could Not Duplicate Concern	511990	F	Per Ilion - Repair at n/c
13307	SEVEN	N/A	308 WIN	29-Aug-88	N	S		15-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512047	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13321	700	not avail.	22-250 REM	24-Apr-69	N	PI/S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512105	F	
13317	700	60560	22-250 REM	31-Aug-15	N	5	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512104	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13312	700	N/A	25-06 REM	31-Mar-78	N	S		18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512109	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13327	700	25789	25-06 REM	4-Feb-86	N	s		27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512099	F	Per Ilion - Replace TA & test
13328	700	not avail.	25-06 REM	28-May-70	N	s	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512114	F	Per Ilion - Replace TA & test @ n/c

13320	700	25771	270 WIN	25-Oct-91	N	s	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512119	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13324	700	N/A	270 WIN	13-Sep-77	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512101	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13314	700	27525	3006 SPRG	6-Jun-97	N	s	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512106	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13316	700	25773	3006 SPRG	27-May-86	N	S	18-Apr-16	18-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512111	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13323	700	25876	8MM REM MA	18-Feb-98	N	S	18-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512100	F	Per Ilion - Replace TA & test @ n/c
13315	710	27410	3006 SPRG	16-Feb-03	Y	5	18-Apr-16	29-Apr-16	Jar-Off - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	512108	F	Replace w/85842 in exchange
13319	710	27410	3006 SPRG	28-Mar-05	Y	S		18-Apr-16	Unexplained Discharge - No Mention of Safety	Altered Adjustments or	************	F	Per Ilion, replace trigger, repair, check over completely, and test at no
			7mm-08						Position Unexplained Discharge - No Mention of Safety	Could Not Duplicate	512107		charge Per Ilion - Replace TA & test
13329	770	85631	REM	26-Mar-09	Υ	S	18-Apr-16	27-Apr-16	Position	Concern	512113	F	@ n/c
	SPORTSMAN									Could Not Duplicate	2022		Per Ilion, replace trigger, repair, check over completely, and test at no
13326	78 710	26162 27410	270 WIN 3006 SPRG	23-May-84 11-May-04	Y	5	18-Apr-16	30.0007 551	Fired on Safe Release Fired on Safe Release	Concern Altered Adjustments or Components	512097	F	charge Replace w/85846 in exchange
				an italy ar		_	30.10			Altered Adjustments or			Per Ilion - Replace TA & test
13340	700	not avail.	3006 SPRG	23-Jun-78	N	PD/S	20-Apr-16	25-Apr-16	Fired on Safe Release Unexplained Discharge - No Mention of Safety	Components Could Not Duplicate	512191	F	@ n/c Per Ilion - Replace TA & test
13344	700	27131	204 RUGER	15-Feb-06	N	s	20-Apr-16	29-Apr-16	Position	Concern	512186	F	@ n/c
	700	20072000	35 05 DEM	25.1422			20.4	20.00		Could Not Duplicate	543405		Per Ilion - Replace TA & test
13341	700	not avail.	25-06 REM	25-Mar-77 29-May-81	N	S		26-Apr-16	Fired on Safe Release Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	512195 512196	F	@ n/c Per Ilion - Replace TA & test @ n/c
20022000			200000000	Andrews Co.						Altered Adjustments or		J.J.	Per Ilion - Replace TA & test
13346	700	not avail.	308 WIN	1-Jul-67	N	S			Fired on Safe Release Unexplained Discharge - No Mention of Safety	Components Altered Adjustments or	512211	F	@ n/c Per Ilion - Replace TA & test
13347	715	85807	243 WIN	22-Apr-08	Υ	5	20-Apr-16	22-Apr-16	Position	Components Could Not Duplicate	512190	F	@ n/c
13338	870	25568	12 GA	25-Aug-92	N	S	20-Apr-16	22-Apr-16	Fired With Safe ON	Concern	512118	F	Ilion repaired at n/c
13351	600	N/A	6.5MM REM	1-Aug-66	Y	s	21-Apr-16	21-Apr-16	Unexplained Discharge - No Mention of Safety Position	Broken or Missing Parts	512202	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13359	700	27351	223 REM	18-Oct-05	N	s	22-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512281	F	Per llion, replace trigger, repair, check over completely, and test at no charge
13356	700	not avail.	270 WIN	16-Mar-71	N	S	22-Apr-16	28-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512280	F	Per Ilion - Replace TA & test @ n/c
			300 WBY							Could Not Duplicate			
13354	700	25903	MA	25-Jul-89	N	S	22-Apr-16	29-Apr-16		Concern	512244	F	
13358	700	N/A	7MM REM MA	16-Mar-79	N	S	22-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512279	F	
13357	SEVEN	24779	243 WIN	17-Dec-02	N	s	22-Apr-16	22-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512282	F	0
	DD1 # 1D 63	*****	7.63454						First on Bull Marian	Could Not Duplicate	F43360		Consumer Service is
13353	DPMS LR-G2	60556	7.62X51	27-Oct-15	N	S	22-Apr-16	22-Apr-16	Fired on Bolt Closing	Concern Could Not Duplicate	512260	F	refunding purchase price Per Ilion - Replace TA & test
13368	700	not avail.	243 WIN	1-Jun-67	N	PD/S	26-Apr-16	28-Apr-16	Fired on Safe Release	Concern	512378	F	
13373	700	25813	3006 SPRG	25-Jun-02	N	PI/S		26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512338	F	Per Ilion, replace trigger, repair, check over completely, and test at no
			22-250	Tarette Chapter		200			Delayed Firing -	Could Not Duplicate		L.	Per Ilion - Replace TA & test
13366	700	not avail.	REM	1-Dec-69	N	S	26-Apr-16	28-Apr-16	Firearms	Concern	512377	F	@ n/c
13365	700	25771	270 WIN	30-Sep-97	N	s	26-Apr-16	28-Apr-16	Fired on Safe Release	Could Not Duplicate Concern	512402	F	Per Ilion - Replace TA & test @ n/c
13371	700	N/A	270 WIN	1-Jul-67	N	s	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	512380	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13378	700	N/A	300 WIN	30-May-74	N	s	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512346	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13370	700	not avail.	3006 SPRG	1-Jan-67	N	s	26-Apr-16	28-Apr-16	Fired With Safe ON	Could Not Duplicate Concern	512376	E	Per Ilion - Replace TA @ n/c
13374	700	27478	3006 SPRG	11-Sep-96	N	5		28-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512376	F	Per Ilion - Replace TA & test
13377	700	25634	3006 SPRG	31-Aug-87	N	5	26-Apr-16	26-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512334	F	
			200000000	7232	555	- 25	227	2273.5002		Could Not Duplicate	200200	1	Per Ilion - Replace TA & test
13372	700	25818	308 WIN	6-Mar-87	N	5		29-Apr-16	Unexplained Discharge - No Mention of Safety	Concern Altered Adjustments or	512373	F	Per Ilion, replace trigger, repair, check over completely, and test at no
13379	700	N/A	5MM REM 7MM REM	30-Jun-77	N	5	26-Apr-16	26-Apr-16	Position	Components Could Not Duplicate	512332	F	charge Per Ilion - Replace TA & test
13369	700	not avail.	MA	20-Jun-79	N	s	26-Apr-16	28-Apr-16	Fired on Safe Release	Concern	512375	F	@ n/c
13367	710	27410	110000000000000	17-Aug-06		s		28-Apr-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512379	F	Per Ilion - Replace TA & test

									Unexplained Discharge - No	Could Not Duplicate			Per Ilion, replace trigger, repair, check over
13376	SEVEN	24781	260 REM	10-Jan-00	N	s	26-Apr-16	26-Apr-16	Mention of Safety Position	Could Not Duplicate Concern	512336	F	completely, and test at no charge
13375	710	27410	3006 SPRG	16-Apr-01	Y	s	26-Apr-16	9-May-16	Fired on Bolt Closing	Altered Adjustments or Components	512369	F	Replace w/85846 in exchang
	700	05.433	222.0544				27.4		Unexplained Discharge - No Mention of Safety	Could Not Duplicate	512452		Per Ilion, replace trigger, repair, check over completely, and test at no
13394	700	85433	223 REM	29-May-12	N	S	27-Apr-16	27-Apr-16	Position Unexplained	Concern	512453	F	charge Per Ilion, replace trigger,
		722200	122000.000		25.71				Discharge - No Mention of Safety	Could Not Duplicate		723	repair, check over completely, and test at no
13380	700	29709	270 WIN	27-May-00	N	S	27-Apr-16	27-Apr-16	Position Unexplained	Concern	512339	F	charge Per Ilion, replace trigger,
	-					12		1200000	Discharge - No Mention of Safety	Altered Adjustments or			repair, check over completely, and test at no
13381	700	N/A	270 WIN	27-Aug-73	N	5	27-Apr-16	27-Apr-16	Position Unexplained	Components	512436	F	charge Per Ilion, replace trigger,
13389	700	N/A	270 WIN	1-Jul-66	N	5	27-Apr-16	27-Apr-16	Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512435	F	repair, check over completely, and test at no charge
13393	700	N/A	270 WIN	18-Feb-69	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512438	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13384	700	N/A	3006 SPRG	25-Apr-72	N	S	27-Apr-16		Fired on Safe Release	Altered Adjustments or Components	512457	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13387	700	N/A	3006 SPRG	3-Aug-73	N	s	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512431	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13388	700	N/A	3006 SPRG	5-Oct-73	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512433	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13395	700	N/A	6MM REM	23-Feb-73	N	S	27-Apr-16	27-Apr-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512434	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
	700	25000	7MM-08 REM	25 1- 04			27.4	20.1-15	Fired on Entr Dolono	Could Not Duplicate	F42422	F	Per Ilion - Replace TA & test
13382	770	25800 85632	270 WIN	26-Jan-94 5-Sep-12	N	5		29-Apr-16	Fired on Safe Release Unexplained Discharge - No Mention of Safety Position	Concern Could Not Duplicate Concern	512437	F	@ n/c Per Ilion, replace trigger, repair, check over completely, and test at no charge
23303	770	03032	270 19114	230212			27-Mpt-10	27-Mpi-10	FORMOR	Could Not Duplicate	346734		Per Ilion - Replace TA & test
13392	700 ML	27580	50 CAL	21-Jun-96	N	S	27-Apr-16	29-Apr-16	Fired on Safe Release	Concern	512432	F	@ n/c
13385	710	27408	270 WIN	17-Aug-03	Υ	s	27-Apr-16	9-May-16	Fired With Safe ON	Altered Adjustments or Components	512455	F	Replace w/85844 in exchange
13397	700	86477	7.62 NATO	13-Feb-13	N	s	28-Apr-16	28-Apr-16	Fired With Safe ON	Could Not Duplicate Concern	512458	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13403	770	85658	300 WIN MA	15-Mar-13	Υ	s	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512510	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13404	SEVEN	24788	308 WIN	17-Oct-84	N	s	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512509	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13405	700	N/A	243 WIN	30-Apr-71	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512514	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13406	700	26096	300 RUM	22-Feb-00	N	s	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512511	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13407	700	29696	338 WIN MA	4-Mar-97	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512508	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13409	700	N/A	270 WIN	1-Apr-74	N	S	2-May-16	2-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512515	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13410	710	27410	3006 SPRG	31-Aug-01	Y	5	2-May-16	11-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512518	F	Replace w/85846 in exchange
13411	700	25793	3006 SPRG	26-Apr-96	N	s	2-May-16	2-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512517	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
									Unexplained Discharge - No Mention of Safety	Could Not Duplicate			Check over completely, repair as needed, and test at no
13414	700	N/A	3006 SPRG	10-Jun-78	N	5	2-May-16	10-May-16	Position	Concern Could Not Duplicate	512516	F	Per Ilion, replace trigger, repair, check over completely, and test at no
13415	700	N/A	243 WIN	28-Apr-69	N	S	2-May-16	2-May-16	Fired With Safe ON Unexplained Discharge - No Mention of Safety	Concern Could Not Duplicate	512488	F	charge Per Ilion, replace trigger, repair, check over completely, and test at no
13417	700	N/A	270 WIN	5-Jun-72	N	s	3-May-16	3-May-16	Position	Concern	512633	F	charge
13419	700	N/A	270 WIN	1-Oct-68	N	s	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512573	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13420	700	N/A	3006 SPRG	28-Feb-79	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512571	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13421	700	N/A	308 WIN	1-Aug-62	N	s		3-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512576	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13422	700	27478	3006 SPRG	28-Feb-03	N	s		3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512574	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13423	700	N/A	7MM EXP RE	21-Sep-79	N	S		3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512575	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13424	700	26959	270 WIN	7-Nov-94	N	S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512572	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13427	700	26158	22-250 REM	6-Feb-86	N	S	3-May-16	3-May-16	Fired With Safe ON	Altered Adjustments or Components	512578	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13428	700	N/A	3006 SPRG	15-Jun-79	N	s	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512577	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13429	700	N/A	3006 SPRG	4-Mar-74	N	PD/S	3-May-16	3-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512596	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13430	700	27480	MM REM M	28-Nov-01	N	5	3-May-16	3-May-16	Delayed Firing - Firearms	Could Not Duplicate Concern	512594	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13425	870	25569	12 GA	20-Oct-15	N	5	3-May-16		Fired With Safe ON	Could Not Duplicate Concern	512570	F	Repair under warranty
13431	700	not avail.	MM REM M		N	PD/S		10-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512676	F	Replace TA & test @ n/c
13432	700	26259	3006 SPRG	23-Oct-98	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512665	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13433	770	85663	3006 SPRG	6-Oct-10	Y	5	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512664	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13434	H&R HANDI RIFLE	72430	300 BLK OU	P-2012/03/20 P-2012/	Y	s	4-May-16	4-May-16	Fail to Fire	Could Not Duplicate Concern	512693	F	Per Ilion, check over completely, repair, and test at no charge
13436	700	N/A	3006 SPRG	3-Mar-76	N	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512669	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13437	700	N/A	3006 SPRG	22-Jul-75	N	5	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512675	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13438	700	not avail.	270 WIN	23-Feb-72	N	s	4-May-16	6-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512667	F	Per Ilion - Replace TA & test @ n/c
13439	700	N/A	2/3 WIN	26-May-76		5		4-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512671	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13440	SPORTSMAN 78	N/A		23-May-88	Y	5	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512670	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13441	700	N/A	3006 SPRG		N	S		4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512679	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13442	700	N/A	3006 SPRG	1-Jan-65	N	s	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512673	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13443	770	85634	308 WIN	26-May-15	Y	S	4-May-16	4-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512668	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13444	700	27095	3006 SPRG	28-Dec-12	N	s	5-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512717	F	Per Ilion - Replace TA & test @ n/c
13445	700	N/A	25-06 REM	6-May-70	N	s	5-May-16	5-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512712	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13446	700	not avail.	3006 SPRG	27-Aug-71	N	s	10 × 0 1 × 0 × 0 × 0 × 0		Fired on Safe Release	Could Not Duplicate Concern	512733	F	Per Ilion - Replace TA & test @ n/c
										Could Not Duplicate			Per Ilion - Replace TA & test
13447	700	25851	270 WIN	7-Aug-97	N	S	5-May-16	12-May-16	Fired on Bolt Closing	Concern	512713	F	@ n/c
13448	700	not avail.	243 WIN	23-Oct-77	N	s	5-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512708	F	Per Ilion - Replace TA & test @ n/c
									Other - Firearms -	Could Not Duplicate			Per Ilion - Replace TA & test
13449	700	27092	243 WIN	10-Sep-13	N	S	5-May-16	6-May-16	XMP Update	Concern	512715	F	@ n/c
13450	770	85633	3006 SPRG	28-Jul-09	Y	S	F May 16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512716	F	Per Ilion - Replace TA & test
13430	//0	00000	3006 SPRG	20-101-09	1	3	2-ividy-16	23-Way-10		Components	512/16	- 1	W H/C
13451	700	27512	22-250 REM	21-Nov-02	N	s	5-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512707	F	Per Ilion - Replace TA & test @ n/c
13452	700	N/A	22-250 REM	1-May-68	N	s	5-May-16	5-May-16	Fired on Safe Release	Could Not Duplicate Concern	512714	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13460	700	27476	270 WIN	21-Jan-99	N	s	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512794	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13461	770	85632	270 WIN	15-Sep-11	Y	s		23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512795	F	Per Ilion - Replace TA & test
	NOME:				200		1000		24140 2000 VIII VIII	Altered Adjustments or	3772,57753		Per Ilion, replace trigger, repair, check over completely, and test at no
13462	700	N/A	308 WIN	14-May-74 26-Oct-77	N	S	9-May-16	9-May-16	Fired on Bolt Closing Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512750 512792	F	charge Per Ilion, replace trigger, repair, check over completely, and test at no charge
13464	700	N/A	3006 SPRG	26-Jan-77	N	s	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512793	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13465	700 LH	N/A	270 WIN	20-Jan-81	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512791	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13467	700	N/A	308 WIN	23-Mar-76	N	S	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512797	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13469	700	N/A	270 WIN	7-May-73	N	s	9-May-16	9-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512790	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13470	700	not avail.	MM REM M	25-May-76	N	s	9-May-16	17-May-16	Fired on Bolt Closing	Altered Adjustments or Components	512796	F	Per Ilion - Replace TA & test @ n/c
13471	700	not avail.	243 WIN	8-Apr-80	N	5	9-May-16	10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern Could Not Duplicate	512798	F	Per Ilion - Replace TA & test @ n/c
13472	870	81062	12 GA	14-Apr-14	N	PD/S	10-May-16	11-May-16	Fired on Bolt Closing	Concern	512861	c	Per Ilion - Repair & test at n/
13473	700	N/A	270 WIN	24-Jun-76	N	s s		10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512837	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
134/3	700	N/A	270 WIN	24-7011-76	N	3	10-IViay-16	10-Way-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate	312837		Per Ilion, replace trigger, repair, check over completely, and test at no
13474	700	85565	22-250 REM	2-Nov-12	N	S	10-May-16	10-May-16	Position Unexplained Discharge - No	Concern	512838	F	charge Per Ilion, replace trigger, repair, check over
13475	700	N/A	270 WIN	1-Jan-80	N	s	10-May-16	10-May-16	Mention of Safety Position	Could Not Duplicate Concern	512839	F	completely, and test at no charge
13476	700	N/A	308 WIN	5-Jun-75	N	5		10-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512840	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13477	700	26199	25-06 REM	8-Nov-96	N	s		10-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512834	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13478	700	not avail.	3006 SPRG	17-Sep-71	N	s	10 14 15	24 14 16	Delayed Firing - Firearms	Could Not Duplicate	512843	F	Per Ilion - Replace TA & test
	12.11.22							24-May-16	Unexplained Discharge - No Mention of Safety	Concern Could Not Duplicate			@ n/c Per Ilion - Replace TA & test
13479	700	84012	7MM-08 REN	29-Feb-12	N	S	10-May-16	23-May-16	Position	Concern Could Not Duplicate	512841	F	@ n/c Per Ilion - Replace TA & test
13480	700	not avail.	308 WIN	1-Mar-67	N	S	10-May-16	11-May-16	Fired on Safe Release	Concern	512842	F	@ n/c
13481	700	25857	280 REM	27-Jul-95	N	PD/S	10-May-16	23-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512862	F	Replace TA & test @ n/c
13487	700	N/A	300 WIN MA	7-Nov-80	N	s	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Improper Maintenance	512911	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13488	700	not avail.	22-250 REM	1-Mar-66	N	s	12-May-16	24-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512912	F	Per Ilion - Replace TA & test @ n/c

	700					-				Could Not Duplicate			Per Ilion - Replace TA & test
13489	700	27095	3006 SPRG	8-Aug-11	N	S	12-May-16	13-May-16	Fired on Bolt Closing	Concern	512895	F	
13490	710	27408	270 WIN	27-Oct-05	N	s	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512870	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13491	700	29692	MM REM M	8-Apr-96	N	5	12-May-16	25-May-16	Fired on Safe Release	Could Not Duplicate Concern	512869	F	Per Ilion - Replace TA & test @ n/c
13492	700	N/A	'MM REM M.	23-Jul-79	N	s	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512913	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13493	700	N/A	3006 SPRG	1-May-74	N	s	12-May-16	12-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512917	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13494	700	N/A	270 WIN	9-Jan-79	N	s	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512914	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13496	700	N/A	3006 SPRG	25-Aug-76	N	s	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512915	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13497	SEVEN	29553	300 REM SA	7-Oct-02	N	s	12-May-16	12-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	512868	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13498	721	N/A	3006 SPRG	1-Jun-61	Y	s	12-May-16	12-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	512919	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
									Unexplained Discharge - No Mention of Safety	Altered Adjustments or			Per Ilion, replace trigger, repair, check over completely, and test at no
13503	700 SPORTSMAN	N/A	3006 SPRG	14-Mar-77	N	S	16-May-16	16-May-16	Position Unexplained Discharge - No Mention of Safety	Components Could Not Duplicate	512971	F	Per Ilion, replace trigger, repair, check over completely, and test at no
13504	78	26172	223 REM	22-Mar-89	N	S	16-May-16	16-May-16	Position	Concern	512948	F	
13506	700	N/A	3006 SPRG	6-Oct-70	N	s	16-May-16	16-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512973	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13507	700	27478	3006 SPRG	5-Oct-98	N	s	16-May-16	17-May-16	Delayed Firing - Firearms	Could Not Duplicate Concern	512975	F	Per Ilion - Replace TA & test @ n/c
13508	700	not avail.	'MM REM M	\$100000 to 100000	N	s	25. 7/03/03/03	17-May-16	Unexplained Discharge - No Mention of Safety Position	Other - Unspecified or Undetermined - Firearms	512961	F	Per Ilion - Replace TA & test
13509	700	not avail.	270 WIN	13-Apr-76	N	s			Fired on Safe Release	Improper Maintenance	512947	F	Per Ilion - Replace TA & test
13511	700	25803	MM REM M.		N	s		24-May-16	Unexplained Discharge - No Mention of Safety	Could Not Duplicate Concern	512974	F	Per Ilion - Replace TA & test
13512	700	N/A	243 WIN	18-Apr-79	N	5	16-May-16	16-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	512946	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge

13517	700	25813	3006 SPRG	19-Apr-86	N	s	18-May-16	18-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	513011	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13518	710	27408	270 WIN	4-Jan-02	Y	s	18-May-16	18-May-16	Fired on Safe Release	Altered Adjustments or Components	513026	F	Replace w/85844 in exchange
13519	700	25711	308 WIN	30-Nov-04	N	s	18-May-16	18-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	513024	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13521	700	25711	308 WIN	21-Feb-08	N	S	18-May-16	18-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	513023	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13522	700	N/A	6MM REM	1-Jan-75	N	s	18-May-16	18-May-16	Unexplained Discharge - No Mention of Safety Position	Altered Adjustments or Components	513044	F	Per Ilion, replace trigger, repair, check over completely, and test at no charge
13523	700	not avail.	300 WIN MA	14-Dec-81	N	5	18-May-16	19-May-16	Unexplained Discharge - No Mention of Safety Position	Could Not Duplicate Concern	513010	F	Per Ilion - Replace TA & test
13524	700	25711	308 WIN	13-Aug-10	N	s	18-May-16	19-May-16	Fired on Bolt Closing	Could Not Duplicate Concern	513022	F	Per Ilion - Replace TA & test @ n/c
13538	597	26536	17 HMR	20-Nov-02	N	PD/S	19-May-16	19-May-16	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	512849	F	Replace in exchange with Ramac 70723 at no charge
13549	597	26516	17 HMR	31-Jan-05	N	PD/S	23-May-16		My Gun Blew Up	Other - Unexamined		F	
13559	597	26514	17 HMR	15-Jun-04	N	PD/S	25-May-16	25-May-16	My Gun Blew Up	Other - Unspecified or Undetermined - Ammunition	513215	F	Consumer Service is refunding purchase price
13560	597	26516	17 HMR	30-Jan-05	N	PD/S	25-May-16	25-May-16	My Gun Blew Up	Other - Unspecified or Undetermined - Firearms	512901	F	Replace in exchange with Ramac 70783 at no charge
13556	700	20000			N	PI/S	25-May-16		Unexplained Discharge - No Mention of Safety Position	Other - Unexamined		F	